




TDK Corporation

HHM1523C1

| | |
|----------------------|--|
| Part Number: | HHM1523C1 |
| Manufacturer/Brand: | TDK Corporation |
| Product description: | BALUN 880MHZ-960MHZ 50/100 0805 |
| Datasheets: | PDF HHM1523C1.pdf |
| RoHS Status: |  Lead free / RoHS Compliant |
| Ship From: | Hong Kong |
| Shipment Way: | DHL/Fedex/TNT/UPS/EMS |

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of HHM1523C1

| | |
|----------------------------------|--|
| PART NUMBER | HHM1523C1 |
| MANUFACTURER | TDK Corporation |
| DESCRIPTION | BALUN 880MHZ-960MHZ 50/100 0805 |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| DATA SHEET | PDF HHM1523C1.pdf |
| SERIES | HHM |
| RETURN LOSS (MIN) | 10dB |
| PHASE DIFFERENCE | 180° ±10° |
| PACKAGING | Cut Tape (CT) |
| PACKAGE / CASE | 0805 (2012 Metric) |
| OTHER NAMES | 445-3960-1 |
| MOUNTING TYPE | Surface Mount |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited) |
| MANUFACTURER STANDARD LEAD TIME | 12 Weeks |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| INSERTION LOSS (MAX) | 1.1dB |
| IMPEDANCE - UNBALANCED/BALANCED | 50 / 100 Ohm |
| FREQUENCY RANGE | 880MHz ~ 960MHz |
| DETAILED DESCRIPTION | RF Balun 880MHz ~ 960MHz 50 / 100 Ohm 0805 (2012 Metric) |

Related Tags

| | | |
|---|--|---|
| TDK Corporation HHM1523C1 | HHM1523C1 Distributor | HHM1523C1 Supplier |
| HHM1523C1 Price | HHM1523C1 Pictures | HHM1523C1 Image |
| HHM1523C1 PDF Datasheet | HHM1523C1 Download Datasheet | HHM1523C1 Datasheet |
| HHM1523C1 Stock | Buy HHM1523C1 | Buy TDK Corporation HHM1523C1 |
| TDK Corporation HHM1523C1 | TDK Corporation Supplier | TDK Corporation Distributor |
| TDK Corporation HHM1523C1 | | |

Related Products

| | |
|--|---|
|  <p>HHM1526 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0805 In stock: Out stock RFQ</p> |  <p>HHM1524B4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/150 0805 In stock: Out stock RFQ</p> |
|  <p>HHM1524B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0805 In stock: Out stock RFQ</p> |  <p>HHM1521 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 In stock: Out stock RFQ</p> |
|  <p>HHM1534 Manufacturers: TDK Corporation Description: BALUN DUAL 50/200 0805 In stock: Out stock RFQ</p> |  <p>HHM1520 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 In stock: Out stock RFQ</p> |
|  <p>HHM1522B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0805 In stock: Out stock RFQ</p> |  <p>HHM1541E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/75 0805 In stock: Out stock RFQ</p> |
|  <p>HHM1523B3 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/100 0805 In stock: Out stock RFQ</p> |  <p>HHM1525 Manufacturers: TDK Corporation Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805 In stock: Out stock RFQ</p> |
|  <p>HHM1522A7 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0805 In stock: Out stock RFQ</p> |  <p>HHM1520A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805 In stock: Out stock RFQ</p> |