

N/A



No Picture

CDCV857BDGG

Part Number:	CDCV857BDGG
Manufacturer/Brand:	N/A
Product description	IC SSTL-II PLL CLK-DRVR 48-TSSOP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of CDCV857BDGG

PART NUMBER	CDCV857BDGG
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48-TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-14165-5
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857BDGG	CDCV857BDGG Distributor	CDCV857BDGG Supplier
CDCV857BDGG Price	CDCV857BDGG Pictures	CDCV857BDGG Image
CDCV857BDGG PDF Datasheet	CDCV857BDGG Download Datasheet	CDCV857BDGG Datasheet
CDCV857BDGG Stock	Buy CDCV857BDGG	Buy CDCV857BDGG
CDCV857BDGG	Supplier	Distributor

Related Products

 CDCV857ADGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 23270 pcs RFQ	 CDCV857ADGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21400 pcs RFQ
 CDCV857BIDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10910 pcs RFQ	 CDCV857BDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21461 pcs RFQ
 CDCV857BIDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 8726 pcs RFQ	 CDCV857ADGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 13508 pcs RFQ
 CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 4617 pcs RFQ	 CDCV857ADGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 12547 pcs RFQ
 CDCV857BDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 22822 pcs RFQ	 CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 12909 pcs RFQ
 CDCV857AGQLR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4057 pcs RFQ	 CDCV855PWRG4 Manufacturers: N/A Description: IC PLL CLOCK DRVR 2.5V 28TSSOP In stock: 61172 pcs RFQ