



Maxim Integrated




Image may be representation. See specifications for product details.

MAX815LESA

Part Number:	MAX815LESA
Manufacturer/Brand:	Maxim Integrated
Product description	IC MPU SUPRVISOR MPU LP 8SOIC
Datasheets:	 MAX815LESA.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION


Specifications of MAX815LESA

PART NUMBER	MAX815LESA
MANUFACTURER	Maxim Integrated
DESCRIPTION	IC MPU SUPRVISOR MPU LP 8SOIC
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	 MAX815LESA.pdf
VOLTAGE - THRESHOLD	4.7V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	Q3265499A
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 8-SOIC
BASE PART NUMBER	MAX815

Related Tags

Maxim Integrated MAX815LESA	MAX815LESA Distributor	MAX815LESA Supplier
MAX815LESA Price	MAX815LESA Pictures	MAX815LESA Image
MAX815LESA PDF Datasheet	MAX815LESA Download Datasheet	MAX815LESA Datasheet
MAX815LESA Stock	Buy MAX815LESA	Buy Maxim Integrated MAX815LESA
Maxim Integrated MAX815LESA	Maxim Integrated Supplier	Maxim Integrated Distributor
Maxim Integrated MAX815LESA		

Related Products

 MAX815LCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 12 pcs RFQ	 MAX815NCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ
 MAX815NEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ	 MAX815NCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ
 MAX815LEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: Out stock RFQ	 MAX815LESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ
 MAX815LCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 39 pcs RFQ	 MAX815NCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 45 pcs RFQ
 MAX815KESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 63 pcs RFQ	 MAX815LESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 48 pcs RFQ
 MAX815LCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ	 MAX815KESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ