

N/A

CDCV857AGQLR

Part Number: CDCV857AGQLR
 Manufacturer/Brand: N/A
 Product description: IC SSTL-II PLL CLK-DRVR 56-BGA
 Datasheets:
 RoHS Status: Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS



[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of CDCV857AGQLR

PART NUMBER	CDCV857AGQLR
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 56-BGA
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	56-BGA MICROSTAR JUNIOR (7.0x4.5)
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	56-VFBGA
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-13775-1
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	180MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857AGQLR	CDCV857AGQLR Distributor	CDCV857AGQLR Supplier
CDCV857AGQLR Price	CDCV857AGQLR Pictures	CDCV857AGQLR Image
CDCV857AGQLR PDF Datasheet	CDCV857AGQLR Download Datasheet	CDCV857AGQLR Datasheet
CDCV857AGQLR Stock	Buy CDCV857AGQLR	Buy CDCV857AGQLR
CDCV857AGQLR	Supplier	Distributor

Related Products

<p>CDCV857BDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21461 pcs RFQ</p>	<p>CDCV857ADGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 12547 pcs RFQ</p>
<p>CDCV857BDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 22822 pcs RFQ</p>	<p>CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 12909 pcs RFQ</p>
<p>CDCV855PWRG4 Manufacturers: N/A Description: IC PLL CLOCK DRVR 2.5V 28TSSOP In stock: 61172 pcs RFQ</p>	<p>CDCV855PWR Manufacturers: N/A Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP In stock: 58925 pcs RFQ</p>
<p>CDCV857BDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 19360 pcs RFQ</p>	<p>CDCV857ADGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 13508 pcs RFQ</p>
<p>CDCV857ADGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21400 pcs RFQ</p>	<p>CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 4617 pcs RFQ</p>
<p>CDCV857ADGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 23270 pcs RFQ</p>	<p>CDCV857BIDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10910 pcs RFQ</p>