



Intersil

X9315TMT1

Part Number:	X9315TMT1
Manufacturer/Brand:	Intersil
Product description:	IC XDCP 32-TAP 100K 3WIRE 8-MSOP
Datasheets:	PDF X9315TMT1.pdf
RoHS Status:	Contains lead / RoHS non-compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of X9315TMT1

PART NUMBER	X9315TMT1
MANUFACTURER	Intersil
DESCRIPTION	IC XDCP 32-TAP 100K 3WIRE 8-MSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	PDF X9315TMT1.pdf
VOLTAGE - SUPPLY	5V
TOLERANCE	±20%
TEMPERATURE COEFFICIENT (TYP)	±300 ppm/°C
TAPER	Linear
SUPPLIER DEVICE PACKAGE	8-MSOP
SERIES	XDCP™
RESISTANCE - WIPER (OHMS) (TYP)	200
RESISTANCE (OHMS)	100k
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
OPERATING TEMPERATURE	0°C ~ 70°C
NUMBER OF TAPS	32
NUMBER OF CIRCUITS	1
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
MEMORY TYPE	Non-Volatile
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INTERFACE	Up/Down (U/D, INC, CS)
FEATURES	-
DETAILED DESCRIPTION	Digital Potentiometer 100k Ohm 1 Circuit 32 Taps Up/Down (U/D, INC, CS) Interface 8-MSOP
CONFIGURATION	Potentiometer
BASE PART NUMBER	X9315

Related Tags

Intersil X9315TMT1	X9315TMT1 Distributor	X9315TMT1 Supplier
X9315TMT1 Price	X9315TMT1 Pictures	X9315TMT1 Image
X9315TMT1 PDF Datasheet	X9315TMT1 Download Datasheet	X9315TMT1 Datasheet
X9315TMT1 Stock	Buy X9315TMT1	Buy Intersil X9315TMT1
Intersil X9315TMT1	Intersil Supplier	Intersil Distributor
Intersil X9315TMT1		

Related Products

<p>X9315TP Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-DIP In stock: Out stock RFQ</p>	<p>X9315TMI-2.7T2 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315TMZ Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315TMIZ-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315TMIT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315TMZ-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315TMZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315TP-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-DIP In stock: Out stock RFQ</p>
<p>X9315TMIZ-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315TMIZ Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315TMZ-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315TMIZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>