



TDK Corporation



HHM1918A2

Part Number:	HHM1918A2
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 2.3GHZ-2.7GHZ 50/100 0402
Datasheets:	 HHM1918A2.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.


Specifications of HHM1918A2

PART NUMBER	HHM1918A2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.3GHZ-2.7GHZ 50/100 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1918A2.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0402 (1005 Metric)
OTHER NAMES	445-175601-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.8dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.3GHz ~ 2.7GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 0402 (1005 Metric)


Related Tags

TDK Corporation HHM1918A2	HHM1918A2 Distributor	HHM1918A2 Supplier
HHM1918A2 Price	HHM1918A2 Pictures	HHM1918A2 Image
HHM1918A2 PDF Datasheet	HHM1918A2 Download Datasheet	HHM1918A2 Datasheet
HHM1918A2 Stock	Buy HHM1918A2	Buy TDK Corporation HHM1918A2
TDK Corporation HHM1918A2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1918A2		

Related Products



HHM2202SA2
Manufacturers: TDK Corporation
Description: RF DIR COUPLER 1.71-1.79GHZ 0603
In stock: Out stock
RFQ



HHM1906A1
Manufacturers: TDK Corporation
Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402
In stock: Out stock
RFQ



HHM1927A4
Manufacturers: TDK Corporation
Description: BALUN 1.805-2.17GHZ 50/100 0402
In stock: Out stock
RFQ



HHM1917A5
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402
In stock: Out stock
RFQ



HHM1946A1
Manufacturers: TDK Corporation
Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402
In stock: Out stock
RFQ



HHM1903A4
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402
In stock: Out stock
RFQ



HHM1904A1
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402
In stock: Out stock
RFQ



HHM22106C1
Manufacturers: TDK Corporation
Description: RF DIR CPLR 700MHZ-2.7GHZ 0603
In stock: Out stock
RFQ



HHM1904C1
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402
In stock: Out stock
RFQ



HHM1932A2
Manufacturers: TDK Corporation
Description: BALUN 862MHZ-894MHZ 50/100 0402
In stock: Out stock
RFQ



HHM1907B1
Manufacturers: TDK Corporation
Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402
In stock: 751 pcs
RFQ



HHM2204SA1
Manufacturers: TDK Corporation
Description: RF DIR COUPLR 1.71-1.785GHZ 0603
In stock: Out stock
RFQ