




TDK Corporation

HHM1524B1

Part Number:	HHM1524B1
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 880MHZ-960MHZ 50/150 0805
Datasheets:	PDF HHM1524B1.pdf
RoHS Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of HHM1524B1

PART NUMBER	HHM1524B1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 880MHZ-960MHZ 50/150 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF HHM1524B1.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3989-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.0dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 150 Ohm
FREQUENCY RANGE	880MHz ~ 960MHz
DETAILED DESCRIPTION	RF Balun 880MHz ~ 960MHz 50 / 150 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1524B1	HHM1524B1 Distributor	HHM1524B1 Supplier
HHM1524B1 Price	HHM1524B1 Pictures	HHM1524B1 Image
HHM1524B1 PDF Datasheet	HHM1524B1 Download Datasheet	HHM1524B1 Datasheet
HHM1524B1 Stock	Buy HHM1524B1	Buy TDK Corporation HHM1524B1
TDK Corporation HHM1524B1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1524B1		

Related Products

 <p>HHM1526 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1522A7 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0805 In stock: Out stock RFQ</p>
 <p>HHM1522B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0805 In stock: Out stock RFQ</p>	 <p>HHM1548E1 Manufacturers: TDK Corporation Description: BALUN 3.2GHZ-3.9GHZ 50/200 0805 In stock: Out stock RFQ</p>
 <p>HHM1534 Manufacturers: TDK Corporation Description: BALUN DUAL 50/200 0805 In stock: Out stock RFQ</p>	 <p>HHM1525 Manufacturers: TDK Corporation Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805 In stock: Out stock RFQ</p>
 <p>HHM1541E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/75 0805 In stock: Out stock RFQ</p>	 <p>HHM1520A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805 In stock: Out stock RFQ</p>
 <p>HHM1523C1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1521 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 In stock: Out stock RFQ</p>
 <p>HHM1524B4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/150 0805 In stock: Out stock RFQ</p>	 <p>HHM1523B3 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/100 0805 In stock: Out stock RFQ</p>