




Anaren

3A512

Part Number:	3A512
Manufacturer/Brand:	Anaren
Product description:	BALUN 1.4GHZ-1.6GHZ 50/50 3SMD
Datasheets:	3A512.pdf
RoHs Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS


[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of 3A512

PART NUMBER	3A512
MANUFACTURER	Anaren
DESCRIPTION	BALUN 1.4GHZ-1.6GHZ 50/50 3SMD
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	3A512.pdf
SERIES	Xinger®
RETURN LOSS (MIN)	15dB
PHASE DIFFERENCE	180° ±5°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	3-SMD, No Lead
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	9 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.3dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	1.4GHz ~ 1.6GHz
DETAILED DESCRIPTION	RF Balun 1.4GHz ~ 1.6GHz 50 / 50 Ohm 3-SMD, No Lead

Related Tags

Anaren 3A512	3A512 Distributor	3A512 Supplier
3A512 Price	3A512 Pictures	3A512 Image
3A512 PDF Datasheet	3A512 Download Datasheet	3A512 Datasheet
3A512 Stock	Buy 3A512	Buy Anaren 3A512
Anaren 3A512	Anaren Supplier	Anaren Distributor
Anaren 3A512		

Related Products

 <p>HHM1710D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>C6198SNL Manufacturers: Pulse Electronics Corporation Description: IC CHIP In stock: Out stock RFQ</p>
 <p>C2021NLT Manufacturers: Pulse Electronics Corporation Description: IC CHIP In stock: Out stock RFQ</p>	 <p>T-075100T Manufacturers: Pulse Electronics Corporation Description: BALUN 1MHZ-1.485GHZ 50/100 6SMD In stock: Out stock RFQ</p>
 <p>CX2332NLT Manufacturers: Pulse Electronics Corporation Description: IC CHIP In stock: Out stock RFQ</p>	 <p>HHM1523B3 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/100 0805 In stock: Out stock RFQ</p>
 <p>MABA-011014 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 45MHZ-1.2GHZ 50/75 4SMD In stock: Out stock RFQ</p>	 <p>0433BM41A0019E Manufacturers: Johanson Technology Description: BALUN 824MHZ-444MHZ 1210 In stock: Out stock RFQ</p>
 <p>BRN6036-0002S Manufacturers: Bourns, Inc. Description: BALUN 5MHZ-1GHZ 6SMD GULL WING In stock: Out stock RFQ</p>	 <p>3A525 Manufacturers: Anaren Description: BALUN 1.5GHZ-1.9GHZ 50/50 3SMD In stock: Out stock RFQ</p>
 <p>CX2038LNLT Manufacturers: Pulse Electronics Corporation Description: BALUN 4.5MHZ-1.5GHZ 75/75 5SMD In stock: Out stock RFQ</p>	 <p>3600BL14M050T Manufacturers: Johanson Technology Description: BALUN 3.3GHZ-3.9GHZ 50/50 0603 In stock: Out stock RFQ</p>