




2450BM15A0002E

Part Number:	2450BM15A0002E
Manufacturer/Brand:	Johanson Technology
Product description:	BALUN 2.4GHZ-2.5GHZ 0805
Datasheets:	 2450BM15A0002E.pdf
RoHS Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of 2450BM15A0002E

PART NUMBER	2450BM15A0002E
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 2450BM15A0002E.pdf
SERIES	-
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Original-Reel®
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	712-1536-6
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	11 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / - Ohm
FREQUENCY RANGE	2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Balun 2.4GHz ~ 2.5GHz 50 / - Ohm 0805 (2012 Metric)

Related Tags

Johanson Technology 2450BM15A0002E	2450BM15A0002E Distributor	2450BM15A0002E Supplier
2450BM15A0002E Price	2450BM15A0002E Pictures	2450BM15A0002E Image
2450BM15A0002E PDF Datasheet	2450BM15A0002E Download Datasheet	2450BM15A0002E Datasheet
2450BM15A0002E Stock	Buy 2450BM15A0002E	Buy Johanson Technology 2450BM15A0002E
Johanson Technology 2450BM15A0002E	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 2450BM15A0002E	Johanson 2450BM15A0002E	Johanson Technology Inc. 2450BM15A0002E

Related Products

 <p>2450BM14A0002T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0603 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM15A0006E Manufacturers: Johanson Technology Description: BALUN 2.45GHZ STLC2690 MATCHED In stock: Out stock</p> <p>RFQ</p>
 <p>2450BM15B0009E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0805 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM15B0003E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0805 In stock: Out stock</p> <p>RFQ</p>
 <p>2450BM18A001E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 1206 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM14G0011T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0603 In stock: Out stock</p> <p>RFQ</p>
 <p>2450BM14E0003T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0603 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM14A0004T Manufacturers: Johanson Technology Description: BALUN MATCHED EIA0603 In stock: Out stock</p> <p>RFQ</p>
 <p>2450BM14E0007T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0603 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM15B0002E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0805 In stock: Out stock</p> <p>RFQ</p>
 <p>2450BM15A0015E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 0805 In stock: Out stock</p> <p>RFQ</p>	 <p>2450BM14B0001T Manufacturers: Johanson Technology Description: BALUN 2.45 GHZ TI CC2430 0603 In stock: Out stock</p> <p>RFQ</p>