



Intersil

X9315UMI-2.7T2

Part Number:	X9315UMI-2.7T2
Manufacturer/Brand:	Intersil
Product description:	IC XDCP 32-TAP 50K 3WIRE 8-MSOP
Datasheets:	PDF X9315UMI-2.7T2.pdf
RoHs Status:	Contains lead / RoHS non-compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of X9315UMI-2.7T2

PART NUMBER	X9315UMI-2.7T2
MANUFACTURER	Intersil
DESCRIPTION	IC XDCP 32-TAP 50K 3WIRE 8-MSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	PDF X9315UMI-2.7T2.pdf
VOLTAGE - SUPPLY	2.7 V ~ 5.5 V
TOLERANCE	±20%
TEMPERATURE COEFFICIENT (TYP)	±300 ppm/°C
TAPER	Linear
SUPPLIER DEVICE PACKAGE	8-MSOP
SERIES	XDCP™
RESISTANCE - WIPER (OHMS) (TYP)	400
RESISTANCE (OHMS)	50k
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF TAPS	32
NUMBER OF CIRCUITS	1
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MEMORY TYPE	Non-Volatile
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INTERFACE	Up/Down (U/D, INC, CS)
FEATURES	-
DETAILED DESCRIPTION	Digital Potentiometer 50k Ohm 1 Circuit 32 Taps Up/Down (U/D, INC, CS) Interface 8-MSOP
CONFIGURATION	Potentiometer
BASE PART NUMBER	X9315

Related Tags

Intersil X9315UMI-2.7T2	X9315UMI-2.7T2 Distributor	X9315UMI-2.7T2 Supplier
X9315UMI-2.7T2 Price	X9315UMI-2.7T2 Pictures	X9315UMI-2.7T2 Image
X9315UMI-2.7T2 PDF Datasheet	X9315UMI-2.7T2 Download Datasheet	X9315UMI-2.7T2 Datasheet
X9315UMI-2.7T2 Stock	Buy X9315UMI-2.7T2	Buy Intersil X9315UMI-2.7T2
Intersil X9315UMI-2.7T2	Intersil Supplier	Intersil Distributor
Intersil X9315UMI-2.7T2		

Related Products

<p>X9315UM-2.7T2 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315UMI-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315UMIZ-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315UMI-2.7 Manufacturers: Intersil Description: IC DIGITAL POT 50K 32TP 8MSOP In stock: Out stock RFQ</p>
<p>X9315UMI Manufacturers: Intersil Description: IC DIGITAL POT 50K 32TP 8MSOP In stock: Out stock RFQ</p>	<p>X9315UMIT2 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315UMIZ Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315UMIT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315UMIZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	<p>X9315UM-2.7T1 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
<p>X9315UM-2.7 Manufacturers: Intersil Description: IC DIGITAL POT 50K 32TP 8MSOP In stock: Out stock RFQ</p>	<p>X9315UMIZ-2.7 Manufacturers: Intersil Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP In stock: Out stock RFQ</p>