



Intersil

## X5001P-2.7A

Part Number:	X5001P-2.7A
Manufacturer/Brand:	Intersil
Product description:	IC SUPERVISOR CPU 8-DIP
Datasheets:	<a href="#">PDF X5001P-2.7A.pdf</a>
RoHs Status:	Contains lead / RoHS non-compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

### Specifications of X5001P-2.7A

PART NUMBER	X5001P-2.7A
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR CPU 8-DIP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	<a href="#">PDF X5001P-2.7A.pdf</a>
VOLTAGE - THRESHOLD	2.92V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	-
RESET TIMEOUT	100 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OUTPUT	Open Drain or Open Collector
OPERATING TEMPERATURE	0°C ~ 70°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 8-PDIP
BASE PART NUMBER	X5001

### Related Tags

<a href="#">Intersil X5001P-2.7A</a>	<a href="#">X5001P-2.7A Distributor</a>	<a href="#">X5001P-2.7A Supplier</a>
<a href="#">X5001P-2.7A Price</a>	<a href="#">X5001P-2.7A Pictures</a>	<a href="#">X5001P-2.7A Image</a>
<a href="#">X5001P-2.7A PDF Datasheet</a>	<a href="#">X5001P-2.7A Download Datasheet</a>	<a href="#">X5001P-2.7A Datasheet</a>
<a href="#">X5001P-2.7A Stock</a>	<a href="#">Buy X5001P-2.7A</a>	<a href="#">Buy Intersil X5001P-2.7A</a>
<a href="#">Intersil X5001P-2.7A</a>	<a href="#">Intersil Supplier</a>	<a href="#">Intersil Distributor</a>
<a href="#">Intersil X5001P-2.7A</a>		

### Related Products

<p><b>X5001PI</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001S8</b> Manufacturers: Intersil Description: IC CPU SUPRV WDT RST LO 8SOIC In stock: Out stock <a href="#">RFQ</a></p>
<p><b>X5001PIZ-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001PZ-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>
<p><b>X5001PI-4.5A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001PI-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>
<p><b>X5001PIZ-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001PZ-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>
<p><b>X5001PIZ-4.5A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001PI-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>
<p><b>X5001P-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>	<p><b>X5001PIZ</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-DIP In stock: Out stock <a href="#">RFQ</a></p>

