




Maxim Integrated

MAX815KEPA+

Part Number: MAX815KEPA+
 Manufacturer/Brand: Maxim Integrated
 Product description: IC SUPERVISOR MPU LP 8-DIP
 Datasheets: [1.MAX815KEPA+.pdf](#)
[2.MAX815KEPA+.pdf](#)
 RoHs Status:  Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.









Specifications of MAX815KEPA+

PART NUMBER	MAX815KEPA+
MANUFACTURER	Maxim Integrated
DESCRIPTION	IC SUPERVISOR MPU LP 8-DIP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	1.MAX815KEPA+.pdf 2.MAX815KEPA+.pdf
VOLTAGE - THRESHOLD	4.8V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OUTPUT	Push-Pull, Totem Pole
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	6 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 8-PDIP
BASE PART NUMBER	MAX815

Related Tags

Maxim Integrated MAX815KEPA+	MAX815KEPA+ Distributor	MAX815KEPA+ Supplier
MAX815KEPA+ Price	MAX815KEPA+ Pictures	MAX815KEPA+ Image
MAX815KEPA+ PDF Datasheet	MAX815KEPA+ Download Datasheet	MAX815KEPA+ Datasheet
MAX815KEPA+ Stock	Buy MAX815KEPA+	Buy Maxim Integrated MAX815KEPA+
Maxim Integrated MAX815KEPA+	Maxim Integrated Supplier	Maxim Integrated Distributor
Maxim Integrated MAX815KEPA+		

Related Products

 <p>MAX815KESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 63 pcs RFQ</p>	 <p>MAX815KESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ</p>
 <p>MAX815LEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: Out stock RFQ</p>	 <p>MAX815LCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ</p>
 <p>MAX814TESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 865 pcs RFQ</p>	 <p>MAX815LCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 12 pcs RFQ</p>
 <p>MAX815KCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ</p>	 <p>MAX815KCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ</p>
 <p>MAX815LCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 39 pcs RFQ</p>	 <p>MAX814TEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 90 pcs RFQ</p>
 <p>MAX815KCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 86 pcs RFQ</p>	 <p>MAX814TESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ</p>

