


A Renesas Company

Intersil



ISL31492EIBZ-T7A

Part Number:	ISL31492EIBZ-T7A
Manufacturer/Brand:	Intersil
Product description	IC TXRX RS485 FAULT PROT 8SOIC
Datasheets:	 ISL31492EIBZ-T7A.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.





Specifications of ISL31492EIBZ-T7A

PART NUMBER	ISL31492EIBZ-T7A
MANUFACTURER	Intersil
DESCRIPTION	IC TXRX RS485 FAULT PROT 8SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 ISL31492EIBZ-T7A.pdf
VOLTAGE - SUPPLY	4.5 V ~ 5.5 V
TYPE	Transceiver
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RECEIVER HYSTERESIS	25mV
PROTOCOL	RS422, RS485
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OTHER NAMES	ISL31492EIBZ-T7ACT
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF DRIVERS/RECEIVERS	1/1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
MANUFACTURER STANDARD LEAD TIME	5 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DUPLEX	Half
DETAILED DESCRIPTION	1/1 Transceiver Half RS422, RS485 8-SOIC
DATA RATE	250kbps
BASE PART NUMBER	ISL31492E

Related Tags

Intersil ISL31492EIBZ-T7A	ISL31492EIBZ-T7A Distributor	ISL31492EIBZ-T7A Supplier
ISL31492EIBZ-T7A Price	ISL31492EIBZ-T7A Pictures	ISL31492EIBZ-T7A Image
ISL31492EIBZ-T7A PDF Datasheet	ISL31492EIBZ-T7A Download Datasheet	ISL31492EIBZ-T7A Datasheet
ISL31492EIBZ-T7A Stock	Buy ISL31492EIBZ-T7A	Buy Intersil ISL31492EIBZ-T7A
Intersil ISL31492EIBZ-T7A	Intersil Supplier	Intersil Distributor
Intersil ISL31492EIBZ-T7A		

Related Products

 ISL31492EIRTZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8TDFN In stock: Out stock RFQ	 ISL31490EIUZ-T7A Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 10MSOP In stock: Out stock RFQ
 ISL31491EIBZ-T7A Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: Out stock RFQ	 ISL31492EIUZ-T Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8MSOP In stock: Out stock RFQ
 ISL31491EIBZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: Out stock RFQ	 ISL31492EIPZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8DIP In stock: Out stock RFQ
 ISL31492EIBZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: Out stock RFQ	 ISL31492EIRTZ-T7A Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8TDFN In stock: Out stock RFQ
 ISL31491EIBZ-T Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: Out stock RFQ	 ISL31492EIBZ-T Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8SOIC In stock: Out stock RFQ
 ISL31492EIUZ Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8MSOP In stock: Out stock RFQ	 ISL31492EIRTZ-T Manufacturers: Intersil Description: IC TXRX RS485 FAULT PROT 8TDFN In stock: Out stock RFQ