




Intersil

X9317TM8I-2.7

Part Number:	X9317TM8I-2.7
Manufacturer/Brand:	Intersil
Product description:	IC XDCP 100TAP 100K 3WIRE 8-MSOP
Datasheets:	PDF X9317TM8I-2.7.pdf
RoHS Status:	 Contains lead / RoHS non-compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of X9317TM8I-2.7

PART NUMBER	X9317TM8I-2.7
MANUFACTURER	Intersil
DESCRIPTION	IC XDCP 100TAP 100K 3WIRE 8-MSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	PDF X9317TM8I-2.7.pdf
VOLTAGE - SUPPLY	2.7 V ~ 5.5 V
TOLERANCE	±20%
TEMPERATURE COEFFICIENT (TYP)	±300 ppm/°C
TAPER	Linear
SUPPLIER DEVICE PACKAGE	8-MSOP
SERIES	XDCP™
RESISTANCE - WIPER (OHMS) (TYP)	400
RESISTANCE (OHMS)	100k
PACKAGING	Tube
PACKAGE / CASE	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF TAPS	100
NUMBER OF CIRCUITS	1
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MEMORY TYPE	Non-Volatile
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INTERFACE	Up/Down (U/D, INC, CS)
FEATURES	-
DETAILED DESCRIPTION	Digital Potentiometer 100k Ohm 1 Circuit 100 Taps Up/Down (U/D, INC, CS) Interface 8-MSOP
CONFIGURATION	Potentiometer
BASE PART NUMBER	X9317

Related Tags

Intersil X9317TM8I-2.7	X9317TM8I-2.7 Distributor	X9317TM8I-2.7 Supplier
X9317TM8I-2.7 Price	X9317TM8I-2.7 Pictures	X9317TM8I-2.7 Image
X9317TM8I-2.7 PDF Datasheet	X9317TM8I-2.7 Download Datasheet	X9317TM8I-2.7 Datasheet
X9317TM8I-2.7 Stock	Buy X9317TM8I-2.7	Buy Intersil X9317TM8I-2.7
Intersil X9317TM8I-2.7	Intersil Supplier	Intersil Distributor
Intersil X9317TM8I-2.7		

Related Products

 <p>X9317TM8I Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	 <p>X9317TM8-2.7 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
 <p>X9317TM8IZ-2.7 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: 214 pcs RFQ</p>	 <p>X9317TM8-2.7T1 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
 <p>X9317TM8-2.7T2 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	 <p>X9317TM8IT1 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
 <p>X9317TM8IZ Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	 <p>X9317TM8IT2 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
 <p>X9315WSZT1 Manufacturers: Intersil Description: IC XDCP 32-TAP 10K 3WIRE 8-SOIC In stock: Out stock RFQ</p>	 <p>X9317TM8I-2.7T2 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>
 <p>X9317TM8I-2.7T1 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>	 <p>X9317TM8 Manufacturers: Intersil Description: IC XDCP 100TAP 100K 3WIRE 8-MSOP In stock: Out stock RFQ</p>

