



IXYS Integrated Circuits Division



Image may be representation. See specifications for product details.

M-982-02P

Part Number:	M-982-02P
Manufacturer/Brand:	IXYS Integrated Circuits Division
Product description	IC TONE DETECTOR SPECIAL 22-DIP
Datasheets:	
RoHS Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of M-982-02P

PART NUMBER	M-982-02P
MANUFACTURER	IXYS Integrated Circuits Division
DESCRIPTION	IC TONE DETECTOR SPECIAL 22-DIP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.7 V ~ 5.5 V
SUPPLIER DEVICE PACKAGE	22-DIP
SERIES	-
PACKAGING	Tube
PACKAGE / CASE	22-DIP (0.415", 10.50mm)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INTERFACE	-
INCLUDES	-
FUNCTION	Tone Detector
DETAILED DESCRIPTION	Telecom IC Tone Detector 22-DIP
CURRENT - SUPPLY	15mA

Related Tags

IXYS Integrated Circuits Division M-982-02P	M-982-02P Distributor	M-982-02P Supplier
M-982-02P Price	M-982-02P Pictures	M-982-02P Image
M-982-02P PDF Datasheet	M-982-02P Download Datasheet	M-982-02P Datasheet
M-982-02P Stock	Buy M-982-02P	Buy IXYS Integrated Circuits Division M-982-02P
IXYS Integrated Circuits Division M-982-02P	IXYS Integrated Circuits Division Supplier	IXYS Integrated Circuits Division Distributor
IXYS Integrated Circuits Division M-982-02P		

Related Products

 M-985 Manufacturers: 3M Description: EARMUFF ASSEMBLY M-985/37333 In stock: 2 pcs RFQ	 M-972 Manufacturers: 3M Description: FLAME RESISTANT HEADGEAR COVER M In stock: 6 pcs RFQ
 M-960 Manufacturers: 3M Description: REPLACEMENT VISOR PIVOT KIT M-96 In stock: 6 pcs RFQ	 M-980-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 16SOIC In stock: Out stock RFQ
 M-984-02P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 14-DIP In stock: Out stock RFQ	 M-982-02S Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 20-SOIC In stock: Out stock RFQ
 M-980-02P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR GEN PURP 8-DIP In stock: Out stock RFQ	 M-976 Manufacturers: 3M Description: HEAD NECK AND SHOULDER COVER M-9 In stock: 5 pcs RFQ
 M-980-02S Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 3V/5V 16SOIC In stock: Out stock RFQ	 M-984-02S Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 16SOIC In stock: Out stock RFQ
 M-984-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 16SOIC In stock: Out stock RFQ	 M-982-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 20-SOIC In stock: Out stock RFQ