




TDK Corporation



HHM1564A4

Part Number:	HHM1564A4
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 824MHZ-894MHZ 50/200 0805
Datasheets:	 HHM1564A4.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of HHM1564A4

PART NUMBER	HHM1564A4
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 824MHZ-894MHZ 50/200 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1564A4.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3993-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	40 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.0dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 200 Ohm
FREQUENCY RANGE	824MHz ~ 894MHz
DETAILED DESCRIPTION	RF Balun 824MHz ~ 894MHz 50 / 200 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1564A4	HHM1564A4 Distributor	HHM1564A4 Supplier
HHM1564A4 Price	HHM1564A4 Pictures	HHM1564A4 Image
HHM1564A4 PDF Datasheet	HHM1564A4 Download Datasheet	HHM1564A4 Datasheet
HHM1564A4 Stock	Buy HHM1564A4	Buy TDK Corporation HHM1564A4
TDK Corporation HHM1564A4	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1564A4		

Related Products



HHM1534
Manufacturers: TDK Corporation
Description: BALUN DUAL 50/200 0805
In stock: Out stock

RFQ



HHM1541E1
Manufacturers: TDK Corporation
Description: BALUN 2.3GHZ-2.5GHZ 50/75 0805
In stock: Out stock

RFQ



HHM1548E1
Manufacturers: TDK Corporation
Description: BALUN 3.2GHZ-3.9GHZ 50/200 0805
In stock: Out stock

RFQ



HHM1589B1
Manufacturers: TDK Corporation
Description: BALUN 470MHZ-710MHZ 6SMD
In stock: Out stock

RFQ



HHM1583B1
Manufacturers: TDK Corporation
Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1595A1
Manufacturers: TDK Corporation
Description: BALUN 3GHZ-8GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1589E1
Manufacturers: TDK Corporation
Description: BALUN 350MHZ-470MHZ 50/200 0805
In stock: Out stock

RFQ



HHM1562B
Manufacturers: TDK Corporation
Description: BALUN 5.15-5.875GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1570B1
Manufacturers: TDK Corporation
Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1526
Manufacturers: TDK Corporation
Description: BALUN 1.71-1.99GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1591D1
Manufacturers: TDK Corporation
Description: BALUN 350MHZ-470MHZ 50/100 0805
In stock: Out stock

RFQ



HHM1525
Manufacturers: TDK Corporation
Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805
In stock: Out stock

RFQ