



TDK Corporation



Image may be representation. See specifications for product details.

HHM22106C1

Part Number:	HHM22106C1
Manufacturer/Brand:	TDK Corporation
Product description	RF DIR CPLR 700MHZ-2.7GHZ 0603
Datasheets:	 HHM22106C1.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION


Specifications of HHM22106C1

PART NUMBER	HHM22106C1
MANUFACTURER	TDK Corporation
DESCRIPTION	RF DIR CPLR 700MHZ-2.7GHZ 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM22106C1.pdf
SERIES	HHM
RETURN LOSS	-
POWER - MAX	-
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric), 6 PC Pad
OTHER NAMES	445-172642-2
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
ISOLATION	-
INSERTION LOSS	0.2dB
FREQUENCY	700MHz ~ 2.7GHz
DETAILED DESCRIPTION	RF Directional Coupler 700MHz ~ 2.7GHz 28.5dB 0603 (1608 Metric), 6 PC Pad
COUPLING FACTOR	28.5dB
COUPLER TYPE	Standard
APPLICATIONS	-

Related Tags

TDK Corporation HHM22106C1	HHM22106C1 Distributor	HHM22106C1 Supplier
HHM22106C1 Price	HHM22106C1 Pictures	HHM22106C1 Image
HHM22106C1 PDF Datasheet	HHM22106C1 Download Datasheet	HHM22106C1 Datasheet
HHM22106C1 Stock	Buy HHM22106C1	Buy TDK Corporation HHM22106C1
TDK Corporation HHM22106C1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM22106C1		

Related Products

 HHM2215SA5 Manufacturers: TDK Corporation Description: RF DIR COUPLER 824-915MHZ 0603 In stock: Out stock RFQ	 HHM2293A1 Manufacturers: TDK Corporation Description: MULTILAYER DIVIDER FOR W-LAN/BLU In stock: Out stock RFQ
 HHM2220SA3 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.92-1.98GHZ 0603 In stock: Out stock RFQ	 HHM22152A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 450-3800MHZ 1608 In stock: Out stock RFQ
 HHM2319B2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 824-915MHZ 0805 In stock: Out stock RFQ	 HHM1932A2 Manufacturers: TDK Corporation Description: BALUN 862MHZ-894MHZ 50/100 0402 In stock: Out stock RFQ
 HHM1946A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: Out stock RFQ	 HHM1918A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: Out stock RFQ
 HHM2204SA1 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 In stock: Out stock RFQ	 HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: Out stock RFQ
 HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71-1.79GHZ 0603 In stock: Out stock RFQ	 HHM22137A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 698-2620MHZ 0603 In stock: Out stock RFQ