

N/A



No Picture

CDCV857BIDGG

Part Number:	CDCV857BIDGG
Manufacturer/Brand:	N/A
Product description	IC SSTL-II PLL CLK-DRVR 48-TSSOP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.



Specifications of CDCV857BIDGG

PART NUMBER	CDCV857BIDGG
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48-TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-13857-5
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857BIDGG	CDCV857BIDGG Distributor	CDCV857BIDGG Supplier
CDCV857BIDGG Price	CDCV857BIDGG Pictures	CDCV857BIDGG Image
CDCV857BIDGG PDF Datasheet	CDCV857BIDGG Download Datasheet	CDCV857BIDGG Datasheet
CDCV857BIDGG Stock	Buy CDCV857BIDGG	Buy CDCV857BIDGG
CDCV857BIDGG	Supplier	Distributor

Related Products

 No Picture CDCV857BIDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 16291 pcs RFQ	 No Picture CDCV857BDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 19360 pcs RFQ
 No Picture CDCV857DGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 4677 pcs RFQ	 No Picture CDCV857BDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 12909 pcs RFQ
 No Picture CDCV857BIDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19369 pcs RFQ	 No Picture CDCV857AGQLR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 56-BGA In stock: 4057 pcs RFQ
 No Picture CDCV857BIDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 8726 pcs RFQ	 No Picture CDCV857BDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 21461 pcs RFQ
 No Picture CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 4617 pcs RFQ	 No Picture CDCV857DGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 5034 pcs RFQ
 No Picture CDCV857BDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 22822 pcs RFQ	 No Picture CDCV857DGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 5363 pcs RFQ