



X5323V14I-4.5A

Part Number:	X5323V14I-4.5A
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR CPU 32K EE 14TSSOP
Datasheets:	 X5323V14I-4.5A.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of X5323V14I-4.5A

PART NUMBER	X5323V14I-4.5A
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR CPU 32K EE 14TSSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	 X5323V14I-4.5A.pdf
VOLTAGE - THRESHOLD	4.63V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	14-TSSOP
SERIES	-
RESET TIMEOUT	100 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	14-TSSOP (0.173", 4.40mm Width)
OUTPUT	Open Drain or Open Collector
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 14-TSSOP
BASE PART NUMBER	X5323

Related Tags

Intersil X5323V14I-4.5A	X5323V14I-4.5A Distributor	X5323V14I-4.5A Supplier
X5323V14I-4.5A Price	X5323V14I-4.5A Pictures	X5323V14I-4.5A Image
X5323V14I-4.5A PDF Datasheet	X5323V14I-4.5A Download Datasheet	X5323V14I-4.5A Datasheet
X5323V14I-4.5A Stock	Buy X5323V14I-4.5A	Buy Intersil X5323V14I-4.5A
Intersil X5323V14I-4.5A	Intersil Supplier	Intersil Distributor
Intersil X5323V14I-4.5A		

Related Products

 X5323V14-2.7T1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ	 X5325P-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ
 X5325P Manufacturers: Intersil Description: IC CPU SUPRV 32K EE RST HI 8DIP In stock: Out stock RFQ	 X5323V14I-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ
 X5323V14-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ	 X5323V14I Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ
 X5325P-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ	 X5325P-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ
 X5323V14I-2.7T1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ	 X5323V14I-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ
 X5323V14T1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ	 X5323V14IT1 Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ