




TDK Corporation



HHM1518A3

Part Number:	HHM1518A3
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 1.71-1.99GHZ 50/150 0805
Datasheets:	 HHM1518A3.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION


Specifications of HHM1518A3

PART NUMBER	HHM1518A3
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 1.71-1.99GHZ 50/150 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1518A3.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3984-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.0dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 150 Ohm
FREQUENCY RANGE	1.71GHz ~ 1.99GHz
DETAILED DESCRIPTION	RF Balun 1.71GHz ~ 1.99GHz 50 / 150 Ohm 0805 (2012 Metric)

Related Tags


TDK Corporation HHM1518A3	HHM1518A3 Distributor	HHM1518A3 Supplier
HHM1518A3 Price	HHM1518A3 Pictures	HHM1518A3 Image
HHM1518A3 PDF Datasheet	HHM1518A3 Download Datasheet	HHM1518A3 Datasheet
HHM1518A3 Stock	Buy HHM1518A3	Buy TDK Corporation HHM1518A3
TDK Corporation HHM1518A3	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1518A3		

Related Products




HHM1516
Manufacturers: TDK Corporation
Description: BALUN 1.71-1.99GHZ 50/200 0805
In stock: Out stock

RFQ



HHM1517A2
Manufacturers: TDK Corporation
Description: BALUN 2.3GHZ-2.5GHZ 50/50 0805
In stock: Out stock

RFQ




HHM1522B1
Manufacturers: TDK Corporation
Description: BALUN 880MHZ-960MHZ 50/50 0805
In stock: Out stock

RFQ




HHM15112A1
Manufacturers: TDK Corporation
Description: BALUN 900MHZ-2.2GHZ 75/100 0805
In stock: Out stock

RFQ




HHM1517
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805
In stock: Out stock

RFQ




HHM1522A7
Manufacturers: TDK Corporation
Description: BALUN 824MHZ-894MHZ 50/50 0805
In stock: Out stock

RFQ



HHM1523B3
Manufacturers: TDK Corporation
Description: BALUN 824MHZ-894MHZ 50/100 0805
In stock: Out stock

RFQ




HHM1520
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1506
Manufacturers: TDK Corporation
Description: BALUN DUAL 50/100 0805
In stock: Out stock

RFQ



HHM1515B2
Manufacturers: TDK Corporation
Description: BALUN 880MHZ-960MHZ 50/200 0805
In stock: Out stock

RFQ



HHM1520A2
Manufacturers: TDK Corporation
Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1521
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805
In stock: Out stock

RFQ