



Intersil

X9261US24I

Part Number:	X9261US24I
Manufacturer/Brand:	Intersil
Product description:	IC XDCP DUAL 256TAP 50K 24-SOIC
Datasheets:	PDF X9261US24I.pdf
RoHS Status:	Contains lead / RoHS non-compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of X9261US24I

PART NUMBER	X9261US24I
MANUFACTURER	Intersil
DESCRIPTION	IC XDCP DUAL 256TAP 50K 24-SOIC
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	PDF X9261US24I.pdf
VOLTAGE - SUPPLY	5V
TOLERANCE	±20%
TEMPERATURE COEFFICIENT (TYP)	±300 ppm/°C
TAPER	Linear
SUPPLIER DEVICE PACKAGE	24-SOIC
SERIES	XDCP™
RESISTANCE - WIPER (OHMS) (TYP)	150 (Max)
RESISTANCE (OHMS)	50k
PACKAGING	Tube
PACKAGE / CASE	24-SOIC (0.295", 7.50mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF TAPS	256
NUMBER OF CIRCUITS	2
MOISTURE SENSITIVITY LEVEL (MSL)	5 (48 Hours)
MEMORY TYPE	Non-Volatile
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INTERFACE	SPI
FEATURES	Selectable Address
DETAILED DESCRIPTION	Digital Potentiometer 50k Ohm 2 Circuit 256 Taps SPI Interface 24-SOIC
CONFIGURATION	Potentiometer
BASE PART NUMBER	X9261

Related Tags

Intersil X9261US24I	X9261US24I Distributor	X9261US24I Supplier
X9261US24I Price	X9261US24I Pictures	X9261US24I Image
X9261US24I PDF Datasheet	X9261US24I Download Datasheet	X9261US24I Datasheet
X9261US24I Stock	Buy X9261US24I	Buy Intersil X9261US24I
Intersil X9261US24I	Intersil Supplier	Intersil Distributor
Intersil X9261US24I		

Related Products

<p>X9261US24IT1 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>	<p>X9261US24-2.7T1 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>
<p>X9261TV24I Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 100K 24TSSOP In stock: Out stock RFQ</p>	<p>X9261US24IZ-2.7 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>
<p>X9261US24 Manufacturers: Intersil Description: IC DCP DUAL 50K 256TP 24SOIC In stock: Out stock RFQ</p>	<p>X9261US24-2.7 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>
<p>X9261US24IZ-2.7T1 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>	<p>X9261US24I-2.7 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>
<p>X9261US24IZ Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>	<p>X9261US24I-2.7T1 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 50K 24-SOIC In stock: Out stock RFQ</p>
<p>X9261TV24-2.7 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 100K 24TSSOP In stock: Out stock RFQ</p>	<p>X9261TV24 Manufacturers: Intersil Description: IC XDCP DUAL 256TAP 100K 24TSSOP In stock: Out stock RFQ</p>

