



Exar Corporation



SP809EK-L-2-9/TR

Part Number:	SP809EK-L-2-9/TR
Manufacturer/Brand:	Exar Corporation
Product description	IC MPU RESET CIRC 2.9V SOT23-3
Datasheets:	PDF SP809EK-L-2-9/TR.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of SP809EK-L-2-9/TR

PART NUMBER	SP809EK-L-2-9/TR
MANUFACTURER	Exar Corporation
DESCRIPTION	IC MPU RESET CIRC 2.9V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF SP809EK-L-2-9/TR.pdf
VOLTAGE - THRESHOLD	2.9V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Original-Reel®
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	1016-1599-6
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3

Related Tags

Exar Corporation SP809EK-L-2-9/TR	SP809EK-L-2-9/TR Distributor	SP809EK-L-2-9/TR Supplier
SP809EK-L-2-9/TR Price	SP809EK-L-2-9/TR Pictures	SP809EK-L-2-9/TR Image
SP809EK-L-2-9/TR PDF Datasheet	SP809EK-L-2-9/TR Download Datasheet	SP809EK-L-2-9/TR Datasheet
SP809EK-L-2-9/TR Stock	Buy SP809EK-L-2-9/TR	Buy Exar Corporation SP809EK-L-2-9/TR
Exar Corporation SP809EK-L-2-9/TR	Exar Corporation Supplier	Exar Corporation Distributor
Exar Corporation SP809EK-L-2-9/TR		

Related Products

 SP809EK-L-3-1/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 3.1V SOT23-3 In stock: 2 pcs RFQ	 SP803WOT Manufacturers: Apex Tool Group Description: SOLDERING IRON 80W 120V In stock: Out stock RFQ
 SP809NEK-L-2-9/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 2.9V SOT23-3 In stock: Out stock RFQ	 SP809EK-L-2-3/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 2.3V SOT23-3 In stock: Out stock RFQ
 SP809EK-L-4-6/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 4.6V SOT23-3 In stock: Out stock RFQ	 SP809EK-L-2-6/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 2.6V SOT23-3 In stock: Out stock RFQ
 SP8008-08UTG Manufacturers: Hamlin / Littelfuse Description: TVS DIODE 5V 12.45V 14UDFN In stock: Out stock RFQ	 SP809NEK-L-4-6/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 4.6V SOT23-3 In stock: Out stock RFQ
 SP80NUS Manufacturers: Apex Tool Group Description: SOLDERING IRON 80W 120V In stock: 56 pcs RFQ	 SP809NEK-L-4-6 Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 4.6V SOT23-3 In stock: Out stock RFQ
 SP809NEK-L-3-1/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 3.1V SOT23-3 In stock: Out stock RFQ	 SP809NEK-L-2-3/TR Manufacturers: Exar Corporation Description: IC MPU RESET CIRC 2.3V SOT23-3 In stock: Out stock RFQ