



CDCS504TPWRQ1

Part Number:	CDCS504TPWRQ1
Manufacturer/Brand:	N/A
Product description	CLOCK FREQUENCY MULTIPLIER
Datasheets:	
RoHs Status	Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of CDCS504TPWRQ1

PART NUMBER	CDCS504TPWRQ1
MANUFACTURER	N/A
DESCRIPTION	CLOCK FREQUENCY MULTIPLIER
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	3 V ~ 3.6 V
TYPE	Multiplier
SUPPLIER DEVICE PACKAGE	8-TSSOP
SERIES	Automotive, AEC-Q100
RATIO - INPUT:OUTPUT	1:1
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	8-TSSOP (0.173", 4.40mm Width)
OUTPUT	LVC MOS
OTHER NAMES	296-49596-1
OPERATING TEMPERATURE	-40°C ~ 105°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	LVC MOS
FREQUENCY - MAX	108MHz
DIFFERENTIAL - INPUT:OUTPUT	No/No
DETAILED DESCRIPTION	Clock Multiplier IC 1:1 108MHz 8-TSSOP (0.173", 4.40mm Width)

Related Tags

CDCS504TPWRQ1	CDCS504TPWRQ1 Distributor	CDCS504TPWRQ1 Supplier
CDCS504TPWRQ1 Price	CDCS504TPWRQ1 Pictures	CDCS504TPWRQ1 Image
CDCS504TPWRQ1 PDF Datasheet	CDCS504TPWRQ1 Download Datasheet	CDCS504TPWRQ1 Datasheet
CDCS504TPWRQ1 Stock	Buy CDCS504TPWRQ1	Buy CDCS504TPWRQ1
CDCS504TPWRQ1	Supplier	Distributor

Related Products

No Picture CDCU2A877ZQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 18331 pcs RFQ	No Picture CDCS502PW Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 60530 pcs RFQ
No Picture CDCU877AGQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 5996 pcs RFQ	No Picture CDCS503PW Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 59861 pcs RFQ
No Picture CDCS503TPWRQ1 Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 84146 pcs RFQ	No Picture CDCU877ARHARG4 Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 22362 pcs RFQ
No Picture CDCU877ARHAR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 8416 pcs RFQ	No Picture CDCU2A877ZQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 21535 pcs RFQ
No Picture CDCS502PWR Manufacturers: N/A Description: IC OSC CLOCK GENERATOR 8-TSSOP In stock: 97003 pcs RFQ	No Picture CDCS503PWR Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 84749 pcs RFQ
No Picture CDCU877AGQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 5841 pcs RFQ	No Picture CDCS502PERF-EVM Manufacturers: N/A Description: EVAL PERFORMANCE MOD FOR CDCS502 In stock: 980 pcs RFQ