

N/A



No Picture

CDCLVP111VFR

Part Number:	CDCLVP111VFR
Manufacturer/Brand:	N/A
Product description	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION












Specifications of CDCLVP111VFR

PART NUMBER	CDCLVP111VFR
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (7x7)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	32-LQFP
OUTPUT	LVPECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	8 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	CML, LVDS, LVPECL, SSTL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-LQFP
BASE PART NUMBER	CDCLVP111

Related Tags

CDCLVP111VFR	CDCLVP111VFR Distributor	CDCLVP111VFR Supplier
CDCLVP111VFR Price	CDCLVP111VFR Pictures	CDCLVP111VFR Image
CDCLVP111VFR PDF Datasheet	CDCLVP111VFR Download Datasheet	CDCLVP111VFR Datasheet
CDCLVP111VFR Stock	Buy CDCLVP111VFR	Buy CDCLVP111VFR
CDCLVP111VFR	Supplier	Distributor

Related Products

 CDCLVP111RHBT Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 11951 pcs RFQ	 CDCLVP111VF Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 16849 pcs RFQ
 CDCLVP1204EVM Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1204 In stock: 611 pcs RFQ	 CDCLVP1208EVM Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1208 In stock: 611 pcs RFQ
 CDCLVP110VFR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 16034 pcs RFQ	 CDCLVP1204RGTT Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 15228 pcs RFQ
 CDCLVP1208RHDT Manufacturers: N/A Description: IC CLK BUFFER 2:8 2GHZ 28VQFN In stock: 11720 pcs RFQ	 CDCLVP1204RGTR Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 29479 pcs RFQ
 CDCLVP110VFRG4 Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 13224 pcs RFQ	 CDCLVP111RHBR Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 14177 pcs RFQ
 CDCLVP111MVFREP Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4428 pcs RFQ	 CDCLVP1208RHDR Manufacturers: N/A Description: IC CLK BUFFER 2:8 2GHZ 28VQFN In stock: 17542 pcs RFQ