



Johanson Technology



2450BL14B100

Part Number:	2450BL14B100
Manufacturer/Brand:	Johanson Technology
Product description	BALUN 2.4GHZ-2.5GHZ 50/100 0603
Datasheets:	 2450BL14B100.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION



Specifications of 2450BL14B100

PART NUMBER	2450BL14B100
MANUFACTURER	Johanson Technology
DESCRIPTION	BALUN 2.4GHZ-2.5GHZ 50/100 0603
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	 2450BL14B100.pdf
SERIES	2450
RETURN LOSS (MIN)	9.5dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Bulk
PACKAGE / CASE	0603 (1608 Metric)
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INSERTION LOSS (MAX)	1.3dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.4GHz ~ 2.5GHz
DETAILED DESCRIPTION	RF Balun 2.4GHz ~ 2.5GHz 50 / 100 Ohm 0603 (1608 Metric)

Related Tags

Johanson Technology 2450BL14B100	2450BL14B100 Distributor	2450BL14B100 Supplier
2450BL14B100 Price	2450BL14B100 Pictures	2450BL14B100 Image
2450BL14B100 PDF Datasheet	2450BL14B100 Download Datasheet	2450BL14B100 Datasheet
2450BL14B100 Stock	Buy 2450BL14B100	Buy Johanson Technology 2450BL14B100
Johanson Technology 2450BL14B100	Johanson Technology Supplier	Johanson Technology Distributor
Johanson Technology 2450BL14B100	Johanson 2450BL14B100	Johanson Technology Inc. 2450BL14B100

Related Products

 2450BL07A0050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ	 2450BL14B100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: Out stock RFQ
 2450BL07A0100T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: Out stock RFQ	 2450BL14B200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 In stock: Out stock RFQ
 2450BL14B050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ	 2450AT45A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: Out stock RFQ
 2450BL15B100E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 In stock: Out stock RFQ	 2450BL05A0100T Manufacturers: Johanson Technology Description: BALUN 2.3GHZ-2.69GHZ 50/100 0202 In stock: Out stock RFQ
 2450BL15B050E Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 In stock: Out stock RFQ	 2450AT44A100E Manufacturers: Johanson Technology Description: RF ANT 2.4GHZ CHIP SOLDER SMD In stock: Out stock RFQ
 2450BL14C050T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ	 2450BL14C200T Manufacturers: Johanson Technology Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 In stock: Out stock RFQ