



Exar Corporation



SP705ICF

Part Number:	SP705ICF
Manufacturer/Brand:	Exar Corporation
Product description	IC SUPERVISOR
Datasheets:	 SP705ICF.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of SP705ICF

PART NUMBER	SP705ICF
MANUFACTURER	Exar Corporation
DESCRIPTION	IC SUPERVISOR
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 SP705ICF.pdf
VOLTAGE - THRESHOLD	4.65V
TYPE	Simple Reset/Power-On Reset
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
OUTPUT	-
NUMBER OF VOLTAGES MONITORED	1
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor 1 Channel

Related Tags

Exar Corporation SP705ICF	SP705ICF Distributor	SP705ICF Supplier
SP705ICF Price	SP705ICF Pictures	SP705ICF Image
SP705ICF PDF Datasheet	SP705ICF Download Datasheet	SP705ICF Datasheet
SP705ICF Stock	Buy SP705ICF	Buy Exar Corporation SP705ICF
Exar Corporation SP705ICF	Exar Corporation Supplier	Exar Corporation Distributor
Exar Corporation SP705ICF		

Related Products

 SP706CN-L/TR Manufacturers: Exar Corporation Description: IC MPU SUPERVISORY CIRCUIT 8SOIC In stock: Out stock RFQ	 SP706CU-L Manufacturers: Exar Corporation Description: IC MPU SUPERVISORY CIRCUIT 8MSOP In stock: Out stock RFQ
 SP705CU-L/TR Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8MSOP In stock: Out stock RFQ	 SP705CN-L Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ
 SP706CN-L Manufacturers: Exar Corporation Description: IC MPU SUPERVISORY CIRCUIT 8SOIC In stock: Out stock RFQ	 SP706CU-L/TR Manufacturers: Exar Corporation Description: IC MPU SUPERVISORY CIRCUIT 8MSOP In stock: Out stock RFQ
 SP705EN-L/TR Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ	 SP706EN-L Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ
 SP705CU-L Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8MSOP In stock: Out stock RFQ	 SP705CN-L/TR Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ
 SP706CN/TR Manufacturers: Exar Corporation Description: IC MPU SUPERVISORY CIRCUIT 8SOIC In stock: Out stock RFQ	 SP705EN-L Manufacturers: Exar Corporation Description: IC SUPERVISOR MPU LP 8SOIC In stock: 25 pcs RFQ