



MAX815NCSA+

|                     |                                                                        |
|---------------------|------------------------------------------------------------------------|
| Part Number:        | MAX815NCSA+                                                            |
| Manufacturer/Brand: | Maxim Integrated                                                       |
| Product description | IC SUPERVISOR MPU LP 8SOIC                                             |
| Datasheets:         | <a href="#">1.MAX815NCSA+.pdf</a><br><a href="#">2.MAX815NCSA+.pdf</a> |
| RoHs Status         | Lead free / RoHS Compliant                                             |
| Ship From           | Hong Kong                                                              |
| Shipment Way        | DHL/Fedex/TNT/UPS/EMS                                                  |

REQUEST FOR QUOTATION

Specifications of MAX815NCSA+

|                                  |                                                                        |
|----------------------------------|------------------------------------------------------------------------|
| PART NUMBER                      | MAX815NCSA+                                                            |
| MANUFACTURER                     | Maxim Integrated                                                       |
| DESCRIPTION                      | IC SUPERVISOR MPU LP 8SOIC                                             |
| LEAD FREE STATUS / ROHS STATUS   | Lead free / RoHS Compliant                                             |
| DATA SHEET                       | <a href="#">1.MAX815NCSA+.pdf</a><br><a href="#">2.MAX815NCSA+.pdf</a> |
| VOLTAGE - THRESHOLD              | 4.55V                                                                  |
| TYPE                             | Simple Reset/Power-On Reset                                            |
| SUPPLIER DEVICE PACKAGE          | 8-SOIC                                                                 |
| SERIES                           | -                                                                      |
| RESET TIMEOUT                    | 140 ms Minimum                                                         |
| RESET                            | Active Low                                                             |
| PACKAGING                        | Tube                                                                   |
| PACKAGE / CASE                   | 8-SOIC (0.154", 3.90mm Width)                                          |
| OUTPUT                           | Push-Pull, Totem Pole                                                  |
| OPERATING TEMPERATURE            | 0°C ~ 70°C (TA)                                                        |
| NUMBER OF VOLTAGES MONITORED     | 1                                                                      |
| MOUNTING TYPE                    | Surface Mount                                                          |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited)                                                          |
| MANUFACTURER STANDARD LEAD TIME  | 6 Weeks                                                                |
| LEAD FREE STATUS / ROHS STATUS   | Lead free / RoHS Compliant                                             |
| DETAILED DESCRIPTION             | Supervisor Push-Pull, Totem Pole 1 Channel 8-SOIC                      |
| BASE PART NUMBER                 | MAX815                                                                 |

Related Tags

|                              |                                |                                  |
|------------------------------|--------------------------------|----------------------------------|
| Maxim Integrated MAX815NCSA+ | MAX815NCSA+ Distributor        | MAX815NCSA+ Supplier             |
| MAX815NCSA+ Price            | MAX815NCSA+ Pictures           | MAX815NCSA+ Image                |
| MAX815NCSA+ PDF Datasheet    | MAX815NCSA+ Download Datasheet | MAX815NCSA+ Datasheet            |
| MAX815NCSA+ Stock            | Buy MAX815NCSA+                | Buy Maxim Integrated MAX815NCSA+ |
| Maxim Integrated MAX815NCSA+ | Maxim Integrated Supplier      | Maxim Integrated Distributor     |
| Maxim Integrated MAX815NCSA+ |                                |                                  |

Related Products

|                                                                                                                                                                            |                                                                                                                                                                             |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <div></div> <div><b>MAX815LCSA+T</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: Out stock<br/><a href="#">RFQ</a></div> | <div></div> <div><b>MAX815NEPA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8-DIP<br/>In stock: 100 pcs<br/><a href="#">RFQ</a></div>     |
| <div></div> <div><b>MAX815LESA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: 48 pcs<br/><a href="#">RFQ</a></div>     | <div></div> <div><b>MAX815TCPA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8-DIP<br/>In stock: 100 pcs<br/><a href="#">RFQ</a></div>     |
| <div></div> <div><b>MAX815LEPA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8-DIP<br/>In stock: Out stock<br/><a href="#">RFQ</a></div>  | <div></div> <div><b>MAX815LESA</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC MPU SUPRVISOR MPU LP 8SOIC<br/>In stock: Out stock<br/><a href="#">RFQ</a></div> |
| <div></div> <div><b>MAX815NCPA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8-DIP<br/>In stock: 100 pcs<br/><a href="#">RFQ</a></div>    | <div></div> <div><b>MAX815TCSA+T</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: Out stock<br/><a href="#">RFQ</a></div>  |
| <div></div> <div><b>MAX815NCSA+T</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: Out stock<br/><a href="#">RFQ</a></div> | <div></div> <div><b>MAX815TCSA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: 482 pcs<br/><a href="#">RFQ</a></div>     |
| <div></div> <div><b>MAX815LESA+T</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: Out stock<br/><a href="#">RFQ</a></div> | <div></div> <div><b>MAX815NESA+</b><br/>Manufacturers: Maxim Integrated<br/>Description: IC SUPERVISOR MPU LP 8SOIC<br/>In stock: 114 pcs<br/><a href="#">RFQ</a></div>     |