


N/A

LM3704YCMM-308/NOPB

Part Number:	LM3704YCMM-308/NOPB
Manufacturer/Brand:	N/A
Product description:	IC MPU SUPERVISOR 3.08V 10MSOP
Datasheets:	
RoHS Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of LM3704YCMM-308/NOPB

PART NUMBER	LM3704YCMM-308/NOPB
MANUFACTURER	N/A
DESCRIPTION	IC MPU SUPERVISOR 3.08V 10MSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - THRESHOLD	3.08V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	10-VSSOP
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
OUTPUT	Open Drain or Open Collector
OTHER NAMES	296-46425-2 LM3704YCMM-308 LM3704YCMM-308/NOPBTR LM3704YCMM-308/NOPBTR-ND LM3704YCMM-308TR LM3704YCMM-308TR-ND LM3704YCMM308NOPB
OPERATING TEMPERATURE	-40°C ~ 85°C (TJ)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	16 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 10-VSSOP
BASE PART NUMBER	LM3704

Related Tags

LM3704YCMM-308/NOPB	LM3704YCMM-308/NOPB Distributor	LM3704YCMM-308/NOPB Supplier
LM3704YCMM-308/NOPB Price	LM3704YCMM-308/NOPB Pictures	LM3704YCMM-308/NOPB Image
LM3704YCMM-308/NOPB PDF Datasheet	LM3704YCMM-308/NOPB Download Datasheet	LM3704YCMM-308/NOPB Datasheet
LM3704YCMM-308/NOPB Stock	Buy LM3704YCMM-308/NOPB	Buy LM3704YCMM-308/NOPB
LM3704YCMM-308/NOPB	Supplier	Distributor

Related Products

 <p>LM3704YBMMX-360 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 4826 pcs</p> <p>RFQ</p>	 <p>LM3704YCMX-232 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 4367 pcs</p> <p>RFQ</p>
 <p>LM3705XBMM-463/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 4.63V 10MSOP In stock: 4531 pcs</p> <p>RFQ</p>	 <p>LM3705XBMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 5958 pcs</p> <p>RFQ</p>
 <p>LM3704YAMX-308 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 5520 pcs</p> <p>RFQ</p>	 <p>LM3704YCMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 62052 pcs</p> <p>RFQ</p>
 <p>LM3704YBMM-360 Manufacturers: N/A Description: IC MPU SUPERVISOR 3.60V 10MSOP In stock: 5384 pcs</p> <p>RFQ</p>	 <p>LM3704YAMM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 4021 pcs</p> <p>RFQ</p>
 <p>LM3705XBBP-232 Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 9MICROSMD In stock: 4612 pcs</p> <p>RFQ</p>	 <p>LM3705XBBP-463 Manufacturers: N/A Description: IC MPU SUPERVISOR 4.63V 9MICROSMD In stock: 3995 pcs</p> <p>RFQ</p>
 <p>LM3704YBMM-360/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.60V 10MSOP In stock: 4947 pcs</p> <p>RFQ</p>	 <p>LM3704YCMX-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 58592 pcs</p> <p>RFQ</p>