



Aeroflex (MACOM Technology Solutions)

Solutions)




Image may be representation. See specifications for product details.

MABA-011015

Part Number:	MABA-011015
Manufacturer/Brand:	Aeroflex (MACOM Technology Solutions)
Product description	BALUN 45MHZ-1.2GHZ 50/75 5SMD
Datasheets:	 MABA-011015.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of MABA-011015

PART NUMBER	MABA-011015
MANUFACTURER	Aeroflex (MACOM Technology Solutions)
DESCRIPTION	BALUN 45MHZ-1.2GHZ 50/75 5SMD
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 MABA-011015.pdf
SERIES	-
RETURN LOSS (MIN)	20dB
PHASE DIFFERENCE	4°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	5-SMD Module
OTHER NAMES	1465-1479-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	10 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.9dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 75 Ohm
FREQUENCY RANGE	45MHz ~ 1.2GHz
DETAILED DESCRIPTION	RF Balun 45MHz ~ 1.2GHz 50 / 75 Ohm 5-SMD Module

Related Tags

Aeroflex (MACOM Technology Solutions) MABA-011015	MABA-011015 Distributor	MABA-011015 Supplier
MABA-011015 Price	MABA-011015 Pictures	MABA-011015 Image
MABA-011015 PDF Datasheet	MABA-011015 Download Datasheet	MABA-011015 Datasheet
MABA-011015 Stock	Buy MABA-011015	Buy Aeroflex (MACOM Technology Solutions) MABA-011015
Aeroflex (MACOM Technology Solutions) MABA-011015	Aeroflex (MACOM Technology Solutions) Supplier	Aeroflex (MACOM Technology Solutions) Distributor
Aeroflex (MACOM Technology Solutions) MABA-011015	Aeroflex Circuit Technology MABA-011015	Aeroflex MABA-011015
Aeroflex (MACOM Technology Solutions) MABA-011015	Aeroflex Metelics, Division of MACOM MABA-011015	M/A-Corn Technology Solutions MABA-011015
Metelics (MACOM Technology Solutions) MABA-011015	MACOM Technology Solutions MABA-011015	

Related Products

 MABA-011002 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-200MHZ 4:1 6SMD In stock: Out stock RFQ	 MABA-011032 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 40MHZ-1GHZ 75/225 6SMD GW In stock: Out stock RFQ
 MABA-011013 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 45MHZ-1.2GHZ 50/75 4SMD In stock: Out stock RFQ	 MABA-011029 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-1.2GHZ 50/75 5SMD MOD In stock: Out stock RFQ
 MABA-011014 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 45MHZ-1.2GHZ 50/75 4SMD In stock: Out stock RFQ	 MABA-010245-CT11TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MABA-010245-CT116 In stock: 3 pcs RFQ
 MABA-010441-CT38A0 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-1.2GHZ 50/75 4SMD MOD In stock: Out stock RFQ	 MABA-011002-TB Manufacturers: Aeroflex (MACOM Technology Solutions) Description: EVAL BOARD FOR MABA-011002 In stock: 3 pcs RFQ
 MABA-011030 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 46MHZ-1GHZ 75/75 MODULE In stock: Out stock RFQ	 MABA-011031 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 5MHZ-1.2GHZ 75/75 MODULE In stock: Out stock RFQ
 MABA-011028 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 600MHZ-1.7GHZ 50/50 MODULE In stock: Out stock RFQ	 MABA-011017 Manufacturers: Aeroflex (MACOM Technology Solutions) Description: BALUN 2:1 6SMD FLAT LEAD In stock: Out stock RFQ