



TDK Corporation



Image may be representation. See specifications for product details.

HHM1589E1

Part Number:	HHM1589E1
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 350MHZ-470MHZ 50/200 0805
Datasheets:	 HHM1589E1.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of HHM1589E1

PART NUMBER	HHM1589E1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 350MHZ-470MHZ 50/200 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1589E1.pdf
SERIES	*
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0805 (2012 Metric), 6 PC Pad
OTHER NAMES	445-175631-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	RF Balun 0805 (2012 Metric), 6 PC Pad

Related Tags

TDK Corporation HHM1589E1	HHM1589E1 Distributor	HHM1589E1 Supplier
HHM1589E1 Price	HHM1589E1 Pictures	HHM1589E1 Image
HHM1589E1 PDF Datasheet	HHM1589E1 Download Datasheet	HHM1589E1 Datasheet
HHM1589E1 Stock	Buy HHM1589E1	Buy TDK Corporation HHM1589E1
TDK Corporation HHM1589E1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1589E1		

Related Products



HHM1603A1
Manufacturers: TDK Corporation
Description: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD
In stock: Out stock

RFQ



HHM1570B1
Manufacturers: TDK Corporation
Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1564A4
Manufacturers: TDK Corporation
Description: BALUN 824MHZ-894MHZ 50/200 0805
In stock: Out stock

RFQ



HHM1562B
Manufacturers: TDK Corporation
Description: BALUN 5.15-5.875GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1583B1
Manufacturers: TDK Corporation
Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805
In stock: Out stock

RFQ




HHM1591D1
Manufacturers: TDK Corporation
Description: BALUN 350MHZ-470MHZ 50/100 0805
In stock: Out stock

RFQ




HHM1548E1
Manufacturers: TDK Corporation
Description: BALUN 3.2GHZ-3.9GHZ 50/200 0805
In stock: Out stock

RFQ




HHM1710D1
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603
In stock: Out stock

RFQ



HHM1711D1
Manufacturers: TDK Corporation
Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603
In stock: 503 pcs

RFQ



HHM1589B1
Manufacturers: TDK Corporation
Description: BALUN 470MHZ-710MHZ 6SMD
In stock: Out stock

RFQ



HHM1595A1
Manufacturers: TDK Corporation
Description: BALUN 3GHZ-8GHZ 50/100 0805
In stock: Out stock

RFQ



HHM1596A1
Manufacturers: TDK Corporation
Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805
In stock: Out stock

RFQ