




TDK Corporation

HHM1591D1

Part Number:	HHM1591D1
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 350MHZ-470MHZ 50/100 0805
Datasheets:	PDF HHM1591D1.pdf
RoHS Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of HHM1591D1

PART NUMBER	HHM1591D1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 350MHZ-470MHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF HHM1591D1.pdf
SERIES	HHM
RETURN LOSS (MIN)	8.5dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3994-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	350MHz ~ 470MHz
DETAILED DESCRIPTION	RF Balun 350MHz ~ 470MHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1591D1	HHM1591D1 Distributor	HHM1591D1 Supplier
HHM1591D1 Price	HHM1591D1 Pictures	HHM1591D1 Image
HHM1591D1 PDF Datasheet	HHM1591D1 Download Datasheet	HHM1591D1 Datasheet
HHM1591D1 Stock	Buy HHM1591D1	Buy TDK Corporation HHM1591D1
TDK Corporation HHM1591D1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1591D1		

Related Products

 <p>HHM1596A1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1711E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ</p>
 <p>HHM1583B1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1603A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD In stock: Out stock RFQ</p>
 <p>HHM1589E1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/200 0805 In stock: Out stock RFQ</p>	 <p>HHM1564A4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/200 0805 In stock: Out stock RFQ</p>
 <p>HHM1595A1 Manufacturers: TDK Corporation Description: BALUN 3GHZ-8GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1589B1 Manufacturers: TDK Corporation Description: BALUN 470MHZ-710MHZ 6SMD In stock: Out stock RFQ</p>
 <p>HHM1710D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>HHM1562B Manufacturers: TDK Corporation Description: BALUN 5.15-5.875GHZ 50/100 0805 In stock: Out stock RFQ</p>
 <p>HHM1711D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 503 pcs RFQ</p>	 <p>HHM1570B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 In stock: Out stock RFQ</p>

