



TLV809L30DBVR

Part Number:	TLV809L30DBVR
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.64V SOT23-3
Datasheets:	
RoHs Status	Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of TLV809L30DBVR

PART NUMBER	TLV809L30DBVR
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.64V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - THRESHOLD	2.64V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	296-39292-2 TLV809L30DBVR-ND
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	8 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809L30

Related Tags

TLV809L30DBVR	TLV809L30DBVR Distributor	TLV809L30DBVR Supplier
TLV809L30DBVR Price	TLV809L30DBVR Pictures	TLV809L30DBVR Image
TLV809L30DBVR PDF Datasheet	TLV809L30DBVR Download Datasheet	TLV809L30DBVR Datasheet
TLV809L30DBVR Stock	Buy TLV809L30DBVR	Buy TLV809L30DBVR
TLV809L30DBVR	Supplier	Distributor

Related Products

TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4436 pcs RFQ	TLV810MDBZR Manufacturers: N/A Description: IC VOLT SUPERISR 4.38V SOT23-3 In stock: 29316 pcs RFQ
TLV810MDBZT Manufacturers: N/A Description: IC VOLT SUPERISR 4.38V SOT23-3 In stock: 198351 pcs RFQ	TLV810RDBZR Manufacturers: N/A Description: IC VOLT SUPERISR 2.64V SOT23-3 In stock: 232600 pcs RFQ
TLV809K33DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 104215 pcs RFQ	TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 206097 pcs RFQ
TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 295751 pcs RFQ	TLV809L30DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 192391 pcs RFQ
TLV809L30DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 251395 pcs RFQ	TLV809K33DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 173753 pcs RFQ
TLV809L30DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 176667 pcs RFQ	TLV809J25DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 118096 pcs RFQ