



LM3704XDMMX-463

Part Number:	LM3704XDMMX-463
Manufacturer/Brand:	N/A
Product description	IC MPU SUPERVISOR 10MSOP
Datasheets:	
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of LM3704XDMMX-463

PART NUMBER	LM3704XDMMX-463
MANUFACTURER	N/A
DESCRIPTION	IC MPU SUPERVISOR 10MSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	
VOLTAGE - THRESHOLD	4.63V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	10-VSSOP
SERIES	-
RESET TIMEOUT	1.12 s Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
OUTPUT	Push-Pull, Totem Pole
OPERATING TEMPERATURE	-40°C ~ 85°C (TJ)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 10-VSSOP
BASE PART NUMBER	LM3704

Related Tags

LM3704XDMMX-463	LM3704XDMMX-463 Distributor	LM3704XDMMX-463 Supplier
LM3704XDMMX-463 Price	LM3704XDMMX-463 Pictures	LM3704XDMMX-463 Image
LM3704XDMMX-463 PDF Datasheet	LM3704XDMMX-463 Download Datasheet	LM3704XDMMX-463 Datasheet
LM3704XDMMX-463 Stock	Buy LM3704XDMMX-463	Buy LM3704XDMMX-463
LM3704XDMMX-463	Supplier	Distributor

Related Products

 No Picture LM3704XDMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 4650 pcs RFQ	 No Picture LM3704XDMMX-220/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 4693 pcs RFQ
 No Picture LM3704YAMM-308/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.08V 10MSOP In stock: 4021 pcs RFQ	 No Picture LM3704XDMMX-232 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 5901 pcs RFQ
 No Picture LM3704XDMM-220/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.20V 10MSOP In stock: 4289 pcs RFQ	 No Picture LM3704YAMMX-308 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 5520 pcs RFQ
 No Picture LM3704XDMM-463/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 4.63V 10MSOP In stock: 5625 pcs RFQ	 No Picture LM3704YBMMX-360 Manufacturers: N/A Description: IC MPU SUPERVISOR 10MSOP In stock: 4826 pcs RFQ
 No Picture LM3704YBMM-360/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 3.60V 10MSOP In stock: 4947 pcs RFQ	 No Picture LM3704XDBP-463 Manufacturers: N/A Description: IC MPU SUPERVISR 4.63V 9MICROSMD In stock: 4202 pcs RFQ
 No Picture LM3704YCMM-232/NOPB Manufacturers: N/A Description: IC MPU SUPERVISOR 2.32V 10MSOP In stock: 62052 pcs RFQ	 No Picture LM3704YBMM-360 Manufacturers: N/A Description: IC MPU SUPERVISOR 3.60V 10MSOP In stock: 5384 pcs RFQ