






X5001V8

| | |
|---------------------|--|
| Part Number: | X5001V8 |
| Manufacturer/Brand: | Intersil |
| Product description | IC SUPERVISOR CPU 8-TSSOP |
| Datasheets: |  X5001V8.pdf |
| RoHs Status |  Contains lead / RoHS non-compliant |
| Ship From | Hong Kong |
| Shipment Way | DHL/Fedex/TNT/UPS/EMS |

REQUEST FOR QUOTATION

Specifications of X5001V8

| | |
|----------------------------------|---|
| PART NUMBER | X5001V8 |
| MANUFACTURER | Intersil |
| DESCRIPTION | IC SUPERVISOR CPU 8-TSSOP |
| LEAD FREE STATUS / ROHS STATUS | Contains lead / RoHS non-compliant |
| DATA SHEET |  X5001V8.pdf |
| VOLTAGE - THRESHOLD | 4.38V |
| TYPE | Simple Reset/Power-On Reset |
| SUPPLIER DEVICE PACKAGE | 8-TSSOP |
| SERIES | - |
| RESET TIMEOUT | 100 ms Minimum |
| RESET | Active Low |
| PACKAGING | Tube |
| PACKAGE / CASE | 8-TSSOP (0.173", 4.40mm Width) |
| OUTPUT | - |
| OPERATING TEMPERATURE | 0°C ~ 70°C (TA) |
| NUMBER OF VOLTAGES MONITORED | 1 |
| MOUNTING TYPE | Surface Mount |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited) |
| LEAD FREE STATUS / ROHS STATUS | Contains lead / RoHS non-compliant |
| DETAILED DESCRIPTION | Supervisor 1 Channel 8-TSSOP |
| BASE PART NUMBER | X5001 |

Related Tags

| | | |
|-----------------------|----------------------------|----------------------|
| Intersil X5001V8 | X5001V8 Distributor | X5001V8 Supplier |
| X5001V8 Price | X5001V8 Pictures | X5001V8 Image |
| X5001V8 PDF Datasheet | X5001V8 Download Datasheet | X5001V8 Datasheet |
| X5001V8 Stock | Buy X5001V8 | Buy Intersil X5001V8 |
| Intersil X5001V8 | Intersil Supplier | Intersil Distributor |
| Intersil X5001V8 | | |

Related Products

| | |
|---|--|
| <div></div> <div>X5001V8-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001V8I-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> |
| <div></div> <div>X5001S8Z Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001S8Z-2.7 Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> |
| <div></div> <div>X5001V8I-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001S8IZ-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> |
| <div></div> <div>X5001S8IZ-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001V8-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> |
| <div></div> <div>X5001V8-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001V8I Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-TSSOP In stock: Out stock <div>RFQ</div></div> |
| <div></div> <div>X5001S8Z-2.7A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> | <div></div> <div>X5001S8Z-4.5A Manufacturers: Intersil Description: IC SUPERVISOR CPU 8-SOIC In stock: Out stock <div>RFQ</div></div> |