




TDK Corporation



HHM1548E1

Part Number:	HHM1548E1
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 3.2GHZ-3.9GHZ 50/200 0805
Datasheets:	 HHM1548E1.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of HHM1548E1

PART NUMBER	HHM1548E1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 3.2GHZ-3.9GHZ 50/200 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1548E1.pdf
SERIES	-
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-173059-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	14 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.2dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 200 Ohm
FREQUENCY RANGE	3.2GHz ~ 3.9GHz
DETAILED DESCRIPTION	RF Balun 3.2GHz ~ 3.9GHz 50 / 200 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1548E1	HHM1548E1 Distributor	HHM1548E1 Supplier
HHM1548E1 Price	HHM1548E1 Pictures	HHM1548E1 Image
HHM1548E1 PDF Datasheet	HHM1548E1 Download Datasheet	HHM1548E1 Datasheet
HHM1548E1 Stock	Buy HHM1548E1	Buy TDK Corporation HHM1548E1
TDK Corporation HHM1548E1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1548E1		

Related Products

 HHM1570B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 In stock: Out stock RFQ	 HHM1589B1 Manufacturers: TDK Corporation Description: BALUN 470MHZ-710MHZ 6SMD In stock: Out stock RFQ
 HHM1589E1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/200 0805 In stock: Out stock RFQ	 HHM1525 Manufacturers: TDK Corporation Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805 In stock: Out stock RFQ
 HHM1526 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0805 In stock: Out stock RFQ	 HHM1534 Manufacturers: TDK Corporation Description: BALUN DUAL 50/200 0805 In stock: Out stock RFQ
 HHM1524B1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0805 In stock: Out stock RFQ	 HHM1564A4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/200 0805 In stock: Out stock RFQ
 HHM1583B1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ	 HHM1562B Manufacturers: TDK Corporation Description: BALUN 5.15-5.875GHZ 50/100 0805 In stock: Out stock RFQ
 HHM1541E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.5GHZ 50/75 0805 In stock: Out stock RFQ	 HHM1524B4 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/150 0805 In stock: Out stock RFQ