





A Renesas Company

Intersil




X5329P

Part Number:	X5329P
Manufacturer/Brand:	Intersil
Product description	IC SUPERVISOR CPU 32K EE 8-DIP
Datasheets:	 X5329P.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of X5329P

PART NUMBER	X5329P
MANUFACTURER	Intersil
DESCRIPTION	IC SUPERVISOR CPU 32K EE 8-DIP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	 X5329P.pdf
VOLTAGE - THRESHOLD	4.38V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-PDIP
SERIES	-
RESET TIMEOUT	100 ms Minimum
RESET	Active High
PACKAGING	Tube
PACKAGE / CASE	8-DIP (0.300", 7.62mm)
OUTPUT	Open Drain or Open Collector
OPERATING TEMPERATURE	0°C ~ 70°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DETAILED DESCRIPTION	Supervisor Open Drain or Open Collector 1 Channel 8-PDIP
BASE PART NUMBER	X5329

Related Tags

Intersil X5329P	X5329P Distributor	X5329P Supplier
X5329P Price	X5329P Pictures	X5329P Image
X5329P PDF Datasheet	X5329P Download Datasheet	X5329P Datasheet
X5329P Stock	Buy X5329P	Buy Intersil X5329P
Intersil X5329P	Intersil Supplier	Intersil Distributor
Intersil X5329P		

Related Products

 <div><b>X5328V14T1</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>	 <div><b>X5329PI</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>
 <div><b>X5329PI-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>	 <div><b>X5328V14I-4.5A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>
 <div><b>X5329PI-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>	 <div><b>X5328V14I-2.7T1</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>
 <div><b>X5328V14I-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>	 <div><b>X5329P-2.7A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>
 <div><b>X5328V14I-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>	 <div><b>X5329P-4.5A</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>
 <div><b>X5329P-2.7</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 8-DIP In stock: Out stock RFQ</div>	 <div><b>X5328V14IT1</b> Manufacturers: Intersil Description: IC SUPERVISOR CPU 32K EE 14TSSOP In stock: Out stock RFQ</div>