



HHM1603A1

Part Number:	HHM1603A1
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 2.3GHZ-2.7GHZ 50/100 4SMD
Datasheets:	HHM1603A1.pdf
RoHs Status	Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of HHM1603A1

PART NUMBER	HHM1603A1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.3GHZ-2.7GHZ 50/100 4SMD
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	HHM1603A1.pdf
SERIES	-
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	4-SMD
OTHER NAMES	445-173060-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.3GHz ~ 2.7GHz
DETAILED DESCRIPTION	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 4-SMD

Related Tags

TDK Corporation HHM1603A1	HHM1603A1 Distributor	HHM1603A1 Supplier
HHM1603A1 Price	HHM1603A1 Pictures	HHM1603A1 Image
HHM1603A1 PDF Datasheet	HHM1603A1 Download Datasheet	HHM1603A1 Datasheet
HHM1603A1 Stock	Buy HHM1603A1	Buy TDK Corporation HHM1603A1
TDK Corporation HHM1603A1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1603A1		

Related Products

HHM1591D1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/100 0805 In stock: Out stock RFQ	HHM1711D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 503 pcs RFQ
HHM1711E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ	HHM1583B1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ
HHM1595A1 Manufacturers: TDK Corporation Description: BALUN 3GHZ-8GHZ 50/100 0805 In stock: Out stock RFQ	HHM17125D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ
HHM1596A1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ	HHM17139B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ
HHM1710D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ	HHM1711Q1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-3.8GHZ 50/100 0603 In stock: Out stock RFQ
HHM1589B1 Manufacturers: TDK Corporation Description: BALUN 470MHZ-710MHZ 6SMD In stock: Out stock RFQ	HHM1589E1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/200 0805 In stock: Out stock RFQ