



ISL88001IH22Z-T7A

Part Number:	ISL88001IH22Z-T7A
Manufacturer/Brand:	Intersil
Product description	IC VOLT SUPERVISOR 2.19V SOT23-3
Datasheets:	 ISL88001IH22Z-T7A.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of ISL88001IH22Z-T7A

PART NUMBER	ISL88001IH22Z-T7A
MANUFACTURER	Intersil
DESCRIPTION	IC VOLT SUPERVISOR 2.19V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 ISL88001IH22Z-T7A.pdf
VOLTAGE - THRESHOLD	2.19V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	ISL88001IH22Z-T7A-ND ISL88001IH22Z-T7ATR ISL88001IH22ZT7A
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	ISL88001

Related Tags

Intersil ISL88001IH22Z-T7A	ISL88001IH22Z-T7A Distributor	ISL88001IH22Z-T7A Supplier
ISL88001IH22Z-T7A Price	ISL88001IH22Z-T7A Pictures	ISL88001IH22Z-T7A Image
ISL88001IH22Z-T7A PDF Datasheet	ISL88001IH22Z-T7A Download Datasheet	ISL88001IH22Z-T7A Datasheet
ISL88001IH22Z-T7A Stock	Buy ISL88001IH22Z-T7A	Buy Intersil ISL88001IH22Z-T7A
Intersil ISL88001IH22Z-T7A	Intersil Supplier	Intersil Distributor
Intersil ISL88001IH22Z-T7A		

Related Products

 ISL88001IH22Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.19V SOT23-3 In stock: Out stock RFQ	 ISL88001IH16Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.58V SOT23-3 In stock: Out stock RFQ
 ISL88001IH17Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.67V SOT23-3 In stock: Out stock RFQ	 ISL88001IH26Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.63V SOT23-3 In stock: Out stock RFQ
 ISL88001IH23Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.32V SOT23-3 In stock: Out stock RFQ	 ISL88001IH16Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.58V SOT23-3 In stock: Out stock RFQ
 ISL88001IH17Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.67V SOT23-3 In stock: Out stock RFQ	 ISL88001IH26Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.63V SOT23-3 In stock: Out stock RFQ
 ISL88001IH23Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.32V SOT23-3 In stock: Out stock RFQ	 ISL88001IH17Z-TK Manufacturers: Intersil Description: IC VOLT SUPERVISOR 1.67V SOT23-3 In stock: Out stock RFQ
 ISL88001IH23Z-T7A Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.32V SOT23-3 In stock: Out stock RFQ	 ISL88001IH22Z-T Manufacturers: Intersil Description: IC VOLT SUPERVISOR 2.19V SOT23-3 In stock: Out stock RFQ