



MAX815TESA+

Part Number:	MAX815TESA+
Manufacturer/Brand:	Maxim Integrated
Product description	IC SUPERVISOR MPU LP 8SOIC
Datasheets:	1.MAX815TESA+.pdf 2.MAX815TESA+.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of MAX815TESA+

PART NUMBER	MAX815TESA+
MANUFACTURER	Maxim Integrated
DESCRIPTION	IC SUPERVISOR MPU LP 8SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	1.MAX815TESA+.pdf 2.MAX815TESA+.pdf
VOLTAGE - THRESHOLD	3.03V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	8-SOIC
SERIES	-
RESET TIMEOUT	140 ms Minimum
RESET	Active Low
PACKAGING	Tube
PACKAGE / CASE	8-SOIC (0.154", 3.90mm Width)
OUTPUT	Push-Pull, Totem Pole
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	6 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel 8-SOIC
BASE PART NUMBER	MAX815

Related Tags

Maxim Integrated MAX815TESA+	MAX815TESA+ Distributor	MAX815TESA+ Supplier
MAX815TESA+ Price	MAX815TESA+ Pictures	MAX815TESA+ Image
MAX815TESA+ PDF Datasheet	MAX815TESA+ Download Datasheet	MAX815TESA+ Datasheet
MAX815TESA+ Stock	Buy MAX815TESA+	Buy Maxim Integrated MAX815TESA+
Maxim Integrated MAX815TESA+	Maxim Integrated Supplier	Maxim Integrated Distributor
Maxim Integrated MAX815TESA+		

Related Products

 MAX815TESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ	 MAX816CSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 114 pcs RFQ
 MAX815TCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ	 MAX816CPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 34 pcs RFQ
 MAX816CSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ	 MAX815TEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ
 MAX815TCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: Out stock RFQ	 MAX816CSA Manufacturers: Maxim Integrated Description: IC MPU SUPERVISORY CIRCUIT 8SOIC In stock: Out stock RFQ
 MAX815TCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 482 pcs RFQ	 MAX815NESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8SOIC In stock: 114 pcs RFQ
 MAX815NEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 100 pcs RFQ	 MAX816EPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU LP 8-DIP In stock: 78 pcs RFQ