



TLV809J25DBZT

Part Number:	TLV809J25DBZT
Manufacturer/Brand:	N/A
Product description	IC VOLT SUPERVISOR 2.25V SOT23-3
Datasheets:	
RoHs Status	Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of TLV809J25DBZT

PART NUMBER	TLV809J25DBZT
MANUFACTURER	N/A
DESCRIPTION	IC VOLT SUPERVISOR 2.25V SOT23-3
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - THRESHOLD	2.25V
TYPE	Simple Reset/Power-On Reset
SUPPLIER DEVICE PACKAGE	SOT-23-3
SERIES	-
RESET TIMEOUT	120 ms Minimum
RESET	Active Low
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	TO-236-3, SC-59, SOT-23-3
OUTPUT	Push-Pull, Totem Pole
OTHER NAMES	296-28209-1
OPERATING TEMPERATURE	-40°C ~ 85°C (TA)
NUMBER OF VOLTAGES MONITORED	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	8 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-3
BASE PART NUMBER	TLV809J25

Related Tags

TLV809J25DBZT	TLV809J25DBZT Distributor	TLV809J25DBZT Supplier
TLV809J25DBZT Price	TLV809J25DBZT Pictures	TLV809J25DBZT Image
TLV809J25DBZT PDF Datasheet	TLV809J25DBZT Download Datasheet	TLV809J25DBZT Datasheet
TLV809J25DBZT Stock	Buy TLV809J25DBZT	Buy TLV809J25DBZT
TLV809J25DBZT	Supplier	Distributor

Related Products

TLV809I50DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 181693 pcs RFQ	TLV809J25DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 240652 pcs RFQ
TLV809KEVM-019 Manufacturers: N/A Description: EVAL MODULE FOR TLV809K33 In stock: 4436 pcs RFQ	TLV809L30DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.64V SOT23-3 In stock: 290593 pcs RFQ
TLV809K33DBZT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 104215 pcs RFQ	TLV809K33DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 173753 pcs RFQ
TLV809K33DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 295751 pcs RFQ	TLV809K33DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.93V SOT23-3 In stock: 206097 pcs RFQ
TLV809I50DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 197608 pcs RFQ	TLV809J25DBVT Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 103290 pcs RFQ
TLV809J25DBVR Manufacturers: N/A Description: IC VOLT SUPERVISOR 2.25V SOT23-3 In stock: 244190 pcs RFQ	TLV809I50DBZR Manufacturers: N/A Description: IC VOLT SUPERVISOR 4.55V SOT23-3 In stock: 224216 pcs RFQ