



TL7770-5CN

Part Number:	TL7770-5CN
Manufacturer/Brand:	N/A
Product description	IC 4.55V DUAL SUPPLY MON 16-DIP
Datasheets:	
RoHs Status	Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.

Specifications of TL7770-5CN

PART NUMBER	TL7770-5CN
MANUFACTURER	N/A
DESCRIPTION	IC 4.55V DUAL SUPPLY MON 16-DIP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - THRESHOLD	5V, Adj
TYPE	Multi-Voltage Supervisor
SUPPLIER DEVICE PACKAGE	16-PDIP
SERIES	-
RESET TIMEOUT	270 ns Typical Propagation Delay
RESET	Active High/Active Low
PACKAGING	Tube
PACKAGE / CASE	16-DIP (0.300", 7.62mm)
OUTPUT	Complementary
OTHER NAMES	296-3266-5
OPERATING TEMPERATURE	0°C ~ 70°C (TA)
NUMBER OF VOLTAGES MONITORED	2
MOUNTING TYPE	Through Hole
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	20 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	Supervisor Complementary 2 Channel 16-PDIP
BASE PART NUMBER	TL7770-5

Related Tags

TL7770-5CN	TL7770-5CN Distributor	TL7770-5CN Supplier
TL7770-5CN Price	TL7770-5CN Pictures	TL7770-5CN Image
TL7770-5CN PDF Datasheet	TL7770-5CN Download Datasheet	TL7770-5CN Datasheet
TL7770-5CN Stock	Buy TL7770-5CN	Buy TL7770-5CN
TL7770-5CN	Supplier	Distributor

Related Products

TL7770-12CDWE4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 4280 pcs RFQ	TL7770-5CDWR Manufacturers: N/A Description: IC DUAL PWR SPLY SUPERVSR 16SOIC In stock: 75518 pcs RFQ
TL7770-51DWRE4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 63077 pcs RFQ	TL7770-12CDW Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 4042 pcs RFQ
TL7770-51DW Manufacturers: N/A Description: IC 4.55V DUAL SUPPLY MON 16-SOIC In stock: 51683 pcs RFQ	TL7770-12CDWR Manufacturers: N/A Description: IC DUAL PWR SPLY SUPRVISO 16SOIC In stock: 48967 pcs RFQ
TL7770-5CNG4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-DIP In stock: 43088 pcs RFQ	TL7770-12CDWG4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 5261 pcs RFQ
TL7770-5CDW Manufacturers: N/A Description: IC 4.55V DUAL SUPPLY MON 16-SOIC In stock: 42637 pcs RFQ	TL7770-51DWR Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 74381 pcs RFQ
TL7770-51DWRG4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 77511 pcs RFQ	TL7770-51DWG4 Manufacturers: N/A Description: IC PS SUPERVISOR DUAL 16-SOIC In stock: 42572 pcs RFQ