



IXYS Integrated Circuits Division



Image may be representation. See specifications for product details.

M-982-02S

Part Number:	M-982-02S
Manufacturer/Brand:	IXYS Integrated Circuits Division
Product description	IC TONE DETECTOR 20-SOIC
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS


REQUEST FOR QUOTATION

Specifications of M-982-02S	
PART NUMBER	M-982-02S
MANUFACTURER	IXYS Integrated Circuits Division
DESCRIPTION	IC TONE DETECTOR 20-SOIC
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.7 V ~ 5.5 V
SUPPLIER DEVICE PACKAGE	20-SOIC
SERIES	-
PACKAGING	Tube
PACKAGE / CASE	20-SOIC (0.295", 7.50mm Width)
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INTERFACE	-
INCLUDES	-
FUNCTION	Tone Detector
DETAILED DESCRIPTION	Telecom IC Tone Detector 20-SOIC
CURRENT - SUPPLY	15mA

Related Tags

IXYS Integrated Circuits Division M-982-02S	M-982-02S Distributor	M-982-02S Supplier
M-982-02S Price	M-982-02S Pictures	M-982-02S Image
M-982-02S PDF Datasheet	M-982-02S Download Datasheet	M-982-02S Datasheet
M-982-02S Stock	Buy M-982-02S	Buy IXYS Integrated Circuits Division M-982-02S
IXYS Integrated Circuits Division M-982-02S	IXYS Integrated Circuits Division Supplier	IXYS Integrated Circuits Division Distributor
IXYS Integrated Circuits Division M-982-02S		

Related Products

 M-972 Manufacturers: 3M Description: FLAME RESISTANT HEADGEAR COVER M In stock: 6 pcs RFQ	 M-982-02P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR SPECIAL 22-DIP In stock: Out stock RFQ
 M-980-02P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR GEN PURP 8-DIP In stock: Out stock RFQ	 M-976 Manufacturers: 3M Description: HEAD NECK AND SHOULDER COVER M-9 In stock: 5 pcs RFQ
 M-980-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 16SOIC In stock: Out stock RFQ	 M-984-02S Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 16SOIC In stock: Out stock RFQ
 M-982-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 20-SOIC In stock: Out stock RFQ	 M-980-02S Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR 3V/5V 16SOIC In stock: Out stock RFQ
 M-985-01P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR PREC 22-DIP In stock: Out stock RFQ	 M-984-02P Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 14-DIP In stock: Out stock RFQ
 M-985 Manufacturers: 3M Description: EARMUFF ASSEMBLY M-985/37333 In stock: 2 pcs RFQ	 M-984-02T Manufacturers: IXYS Integrated Circuits Division Description: IC TONE DETECTOR MONOLITH 16SOIC In stock: Out stock RFQ