


N/A

CDCV857DGG

Part Number:	CDCV857DGG
Manufacturer/Brand:	N/A
Product description:	IC SSTL-II PLL CLK-DRVR 48TSSOP
Datasheets:	
RoHS Status:	 Lead free / RoHS Compliant
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.













Specifications of CDCV857DGG

PART NUMBER	CDCV857DGG
MANUFACTURER	N/A
DESCRIPTION	IC SSTL-II PLL CLK-DRVR 48TSSOP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	2.3 V ~ 2.7 V
TYPE	PLL Clock Driver
SUPPLIER DEVICE PACKAGE	48-TSSOP
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tube
PACKAGE / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
OUTPUT	Clock
OTHER NAMES	296-24143-5 CDCV857DGG-ND
OPERATING TEMPERATURE	0°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	Clock
FREQUENCY - MAX	200MHz
DIVIDER/MULTIPLIER	No/No
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCV857

Related Tags

CDCV857DGG	CDCV857DGG Distributor	CDCV857DGG Supplier
CDCV857DGG Price	CDCV857DGG Pictures	CDCV857DGG Image
CDCV857DGG PDF Datasheet	CDCV857DGG Download Datasheet	CDCV857DGG Datasheet
CDCV857DGG Stock	Buy CDCV857DGG	Buy CDCV857DGG
CDCV857DGG	Supplier	Distributor

Related Products

 <p>CDCV857DGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 5405 pcs</p> <p>RFQ</p>	 <p>CDCVF111FNG4 Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 5389 pcs</p> <p>RFQ</p>
 <p>CDCV857DGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 4677 pcs</p> <p>RFQ</p>	 <p>CDCV857BGQLR Manufacturers: N/A Description: IC 2.5V PLL CLOCK DRVR 56-BGA In stock: 4617 pcs</p> <p>RFQ</p>
 <p>CDCV857BIDGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 16291 pcs</p> <p>RFQ</p>	 <p>CDCV857BDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 22822 pcs</p> <p>RFQ</p>
 <p>CDCVF111FNR Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 7790 pcs</p> <p>RFQ</p>	 <p>CDCV857BIDGGRG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48TSSOP In stock: 19369 pcs</p> <p>RFQ</p>
 <p>CDCV857DGGR Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 5363 pcs</p> <p>RFQ</p>	 <p>CDCV857BIDGGG4 Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 8726 pcs</p> <p>RFQ</p>
 <p>CDCV857BIDGG Manufacturers: N/A Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In stock: 10910 pcs</p> <p>RFQ</p>	 <p>CDCVF111FN Manufacturers: N/A Description: IC CLK BUFFER 1:9 650MHZ 28PLCC In stock: 6603 pcs</p> <p>RFQ</p>