




TDK Corporation

HHM1779B1

Part Number: HHM1779B1
 Manufacturer/Brand: TDK Corporation
 Product description: BALUN 2.11-2.17GHZ 50/100 0603
 Datasheets: [PDF HHM1779B1.pdf](#)
 RoHS Status:  Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS




Image may be representation. See specifications for product details.

[REQUEST FOR QUOTATION](#)













Specifications of HHM1779B1

PART NUMBER	HHM1779B1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 2.11-2.17GHZ 50/100 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF HHM1779B1.pdf
SERIES	-
RETURN LOSS (MIN)	-10dB
PHASE DIFFERENCE	190°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric), 6 PC Pad
OTHER NAMES	445-172639-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.8dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	2.11GHz 2.17GHz
DETAILED DESCRIPTION	RF Balun 2.11GHz 2.17GHz 50 / 100 Ohm 0603 (1608 Metric), 6 PC Pad

Related Tags

TDK Corporation HHM1779B1	HHM1779B1 Distributor	HHM1779B1 Supplier
HHM1779B1 Price	HHM1779B1 Pictures	HHM1779B1 Image
HHM1779B1 PDF Datasheet	HHM1779B1 Download Datasheet	HHM1779B1 Datasheet
HHM1779B1 Stock	Buy HHM1779B1	Buy TDK Corporation HHM1779B1
TDK Corporation HHM1779B1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1779B1		

Related Products

 <p>HHM1791A1 Manufacturers: TDK Corporation Description: BALUN 2.5GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ</p>	 <p>HHM1903A4 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: Out stock RFQ</p>
 <p>HHM1904A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: Out stock RFQ</p>	 <p>HHM1763B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0603 In stock: Out stock RFQ</p>
 <p>HHM1776B2 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>HHM1776B3 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0603 In stock: Out stock RFQ</p>
 <p>HHM1902B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ</p>	 <p>HHM1903A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: Out stock RFQ</p>
 <p>HHM1749S1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0603 In stock: Out stock RFQ</p>	 <p>HHM1752A2 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 In stock: Out stock RFQ</p>
 <p>HHM1902A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ</p>	 <p>HHM1775D1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ</p>

