



A Renesas Company

Intersil



Image may be representation. See specifications for product details.

ICL3223CA

Part Number:	ICL3223CA
Manufacturer/Brand:	Intersil
Product description	IC TXRX 2/2 FULL RS232 20SSOP
Datasheets:	 ICL3223CA.pdf
RoHs Status	 Contains lead / RoHS non-compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Specifications of ICL3223CA

PART NUMBER	ICL3223CA
MANUFACTURER	Intersil
DESCRIPTION	IC TXRX 2/2 FULL RS232 20SSOP
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DATA SHEET	 ICL3223CA.pdf
VOLTAGE - SUPPLY	3 V ~ 5.5 V
TYPE	Transceiver
SUPPLIER DEVICE PACKAGE	20-SSOP
SERIES	-
RECEIVER HYSTERESIS	300mV
PROTOCOL	RS232
PACKAGING	Tube
PACKAGE / CASE	20-SSOP (0.209", 5.30mm Width)
OPERATING TEMPERATURE	0°C ~ 70°C
NUMBER OF DRIVERS/RECEIVERS	2/2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
DUPLEX	Full
DETAILED DESCRIPTION	2/2 Transceiver Full RS232 20-SSOP
DATA RATE	250kbps
BASE PART NUMBER	ICL3223

Related Tags

Intersil ICL3223CA	ICL3223CA Distributor	ICL3223CA Supplier
ICL3223CA Price	ICL3223CA Pictures	ICL3223CA Image
ICL3223CA PDF Datasheet	ICL3223CA Download Datasheet	ICL3223CA Datasheet
ICL3223CA Stock	Buy ICL3223CA	Buy Intersil ICL3223CA
Intersil ICL3223CA	Intersil Supplier	Intersil Distributor
Intersil ICL3223CA		

Related Products

 ICL3223CPZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20DIP In stock: Out stock RFQ	 ICL3223CV Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: Out stock RFQ
 ICL3222IVZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: Out stock RFQ	 ICL3222IVZ-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: Out stock RFQ
 ICL3222IV-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: Out stock RFQ	 ICL3223CAZ Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: Out stock RFQ
 ICL3222IB-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 18SOIC In stock: Out stock RFQ	 ICL3222IB Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 18SOIC In stock: Out stock RFQ
 ICL3222IV Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20TSSOP In stock: Out stock RFQ	 ICL3223CA-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: Out stock RFQ
 ICL3223CP Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20DIP In stock: Out stock RFQ	 ICL3223CAZ-T Manufacturers: Intersil Description: IC TXRX 2/2 FULL RS232 20SSOP In stock: Out stock RFQ