




TDK Corporation

HHM1776B2

Part Number: HHM1776B2
 Manufacturer/Brand: TDK Corporation
 Product description: BALUN 824MHZ-894MHZ 50/50 0603
 Datasheets: [PDF HHM1776B2.pdf](#)
 RoHs Status:  Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS




Image may be representation. See specifications for product details.

[REQUEST FOR QUOTATION](#)













Specifications of HHM1776B2

PART NUMBER	HHM1776B2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 824MHZ-894MHZ 50/50 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF HHM1776B2.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric)
OTHER NAMES	445-6864-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.2dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	824MHz ~ 894MHz
DETAILED DESCRIPTION	RF Balun 824MHz ~ 894MHz 50 / 50 Ohm 0603 (1608 Metric)

Related Tags

TDK Corporation HHM1776B2	HHM1776B2 Distributor	HHM1776B2 Supplier
HHM1776B2 Price	HHM1776B2 Pictures	HHM1776B2 Image
HHM1776B2 PDF Datasheet	HHM1776B2 Download Datasheet	HHM1776B2 Datasheet
HHM1776B2 Stock	Buy HHM1776B2	Buy TDK Corporation HHM1776B2
TDK Corporation HHM1776B2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1776B2		

Related Products

 <p>HHM1732B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603 In stock: Out stock RFQ</p>	 <p>HHM1791A1 Manufacturers: TDK Corporation Description: BALUN 2.5GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ</p>
 <p>HHM1903A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: Out stock RFQ</p>	 <p>HHM1902A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ</p>
 <p>HHM1733B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>HHM1749S1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0603 In stock: Out stock RFQ</p>
 <p>HHM1752A2 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 In stock: Out stock RFQ</p>	 <p>HHM1763B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0603 In stock: Out stock RFQ</p>
 <p>HHM1776B3 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>HHM1779B1 Manufacturers: TDK Corporation Description: BALUN 2.11-2.17GHZ 50/100 0603 In stock: Out stock RFQ</p>
 <p>HHM1775D1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1902B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ</p>