




CDCU877ARHAR

Part Number:	CDCU877ARHAR
Manufacturer/Brand:	N/A
Product description	IC PLL CLOCK DRIVER 1.8V 40VQFN
Datasheets:	
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.











Specifications of CDCU877ARHAR

PART NUMBER	CDCU877ARHAR
MANUFACTURER	N/A
DESCRIPTION	IC PLL CLOCK DRIVER 1.8V 40VQFN
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	
VOLTAGE - SUPPLY	1.7 V ~ 1.9 V
SUPPLIER DEVICE PACKAGE	40-VQFN (6x6)
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	40-VFQFN Exposed Pad
PLL	Yes
OUTPUT	SSTL-18
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
MANUFACTURER STANDARD LEAD TIME	26 Weeks
MAIN PURPOSE	Memory, DDR2
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	SSTL-18
FREQUENCY - MAX	400MHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCU877

Related Tags

CDCU877ARHAR	CDCU877ARHAR Distributor	CDCU877ARHAR Supplier
CDCU877ARHAR Price	CDCU877ARHAR Pictures	CDCU877ARHAR Image
CDCU877ARHAR PDF Datasheet	CDCU877ARHAR Download Datasheet	CDCU877ARHAR Datasheet
CDCU877ARHAR Stock	Buy CDCU877ARHAR	Buy CDCU877ARHAR
CDCU877ARHAR	Supplier	Distributor

Related Products

 No Picture CDCS503TPWRQ1 Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 84146 pcs RFQ	 No Picture CDCU2A877ZQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 21535 pcs RFQ
 No Picture CDCU877ARHARG4 Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 22362 pcs RFQ	 No Picture CDCS504TPWRQ1 Manufacturers: N/A Description: CLOCK FREQUENCY MULTIPLIER In stock: 72667 pcs RFQ
 No Picture CDCU877AGQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 5841 pcs RFQ	 No Picture CDCU877AZQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 20909 pcs RFQ
 No Picture CDCU877ARTBT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40-QFN In stock: 5574 pcs RFQ	 No Picture CDCU877ARTBR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40-QFN In stock: 5776 pcs RFQ
 No Picture CDCU877AGQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 5996 pcs RFQ	 No Picture CDCU877ARHAT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 19322 pcs RFQ
 No Picture CDCU2A877ZQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 18331 pcs RFQ	 No Picture CDCU877ARHATG4 Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 13702 pcs RFQ