




Maxim Integrated



DS21372T+

Part Number:	DS21372T+
Manufacturer/Brand:	Maxim Integrated
Product description	IC TESTER BIT ERROR 3.3V 32-TQFP
Datasheets:	 DS21372T+.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION




Specifications of DS21372T+

PART NUMBER	DS21372T+
MANUFACTURER	Maxim Integrated
DESCRIPTION	IC TESTER BIT ERROR 3.3V 32-TQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 DS21372T+.pdf
VOLTAGE - SUPPLY	3 V ~ 3.6 V
SUPPLIER DEVICE PACKAGE	32-TQFP (7x7)
SERIES	-
PACKAGING	Tray
PACKAGE / CASE	32-TQFP
OPERATING TEMPERATURE	0°C ~ 70°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INTERFACE	T1
INCLUDES	Error Counter, Pattern Generator and Detector
FUNCTION	Bit Error Rate Tester (BERT)
DETAILED DESCRIPTION	Telecom IC Bit Error Rate Tester (BERT) 32-TQFP (7x7)
CURRENT - SUPPLY	10mA
BASE PART NUMBER	DS21372

Related Tags

Maxim Integrated DS21372T+	DS21372T+ Distributor	DS21372T+ Supplier
DS21372T+ Price	DS21372T+ Pictures	DS21372T+ Image
DS21372T+ PDF Datasheet	DS21372T+ Download Datasheet	DS21372T+ Datasheet
DS21372T+ Stock	Buy DS21372T+	Buy Maxim Integrated DS21372T+
Maxim Integrated DS21372T+	Maxim Integrated Supplier	Maxim Integrated Distributor
Maxim Integrated DS21372T+		

Related Products

 DS2141AN Manufacturers: Maxim Integrated Description: IC CONTROLLER T1 5V 40-DIP In stock: Out stock RFQ	 DS2141A Manufacturers: Maxim Integrated Description: IC CONTROLLER T1 5V 40-DIP In stock: Out stock RFQ
 DS2141AQ+ Manufacturers: Maxim Integrated Description: IC CONTROLLER T1 5V 44-PLCC In stock: 32 pcs RFQ	 DS2141AQ Manufacturers: Maxim Integrated Description: IC CONTROLLER T1 5V 44-PLCC In stock: Out stock RFQ
 DS21354LB+ Manufacturers: Maxim Integrated Description: IC TXRX E1 3.3V 100-LQFP In stock: 180 pcs RFQ	 DS21372T Manufacturers: Maxim Integrated Description: IC TESTER BIT ERROR 3.3V 32-TQFP In stock: Out stock RFQ
 DS21354LC1+ Manufacturers: Maxim Integrated Description: IC TXRX E1 3.3V 100-LQFP In stock: 18 pcs RFQ	 DS21354L+ Manufacturers: Maxim Integrated Description: IC TXRX E1 1-CHIP 3.3V 100-LQFP In stock: 160 pcs RFQ
 DS21372TN Manufacturers: Maxim Integrated Description: IC TESTER BIT ERROR 3.3V 32-TQFP In stock: Out stock RFQ	 DS21354LN+ Manufacturers: Maxim Integrated Description: IC TXRX E1 1-CHIP 3.3V 100-LQFP In stock: 1 pcs RFQ
 DS21354LN Manufacturers: Maxim Integrated Description: IC TXRX E1 1-CHIP 3.3V 100-LQFP In stock: Out stock RFQ	 DS21372TN+ Manufacturers: Maxim Integrated Description: IC TESTER BIT ERROR 3.3V 32-TQFP In stock: Out stock RFQ