



TDK Corporation



HHM1775D1

Part Number:	HHM1775D1
Manufacturer/Brand:	TDK Corporation
Product description	BALUN 3.1GHZ-4.9GHZ 50/100 0805
Datasheets:	 HHM1775D1.pdf
RoHs Status	 Lead free / RoHS Compliant
Ship From	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

REQUEST FOR QUOTATION

Image may be representation. See specifications for product details.











Specifications of HHM1775D1

PART NUMBER	HHM1775D1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 3.1GHZ-4.9GHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	 HHM1775D1.pdf
SERIES	*
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric), 6 PC Pad
OTHER NAMES	445-175622-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DETAILED DESCRIPTION	RF Balun 0603 (1608 Metric), 6 PC Pad

Related Tags

TDK Corporation HHM1775D1	HHM1775D1 Distributor	HHM1775D1 Supplier
HHM1775D1 Price	HHM1775D1 Pictures	HHM1775D1 Image
HHM1775D1 PDF Datasheet	HHM1775D1 Download Datasheet	HHM1775D1 Datasheet
HHM1775D1 Stock	Buy HHM1775D1	Buy TDK Corporation HHM1775D1
TDK Corporation HHM1775D1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1775D1		

Related Products

 HHM1732B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603 In stock: Out stock RFQ	 HHM1902B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ
 HHM1733B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0603 In stock: Out stock RFQ	 HHM1749S1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0603 In stock: Out stock RFQ
 HHM1791A1 Manufacturers: TDK Corporation Description: BALUN 2.5GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ	 HHM1731F1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.88GHZ 50/200 0603 In stock: Out stock RFQ
 HHM1779B1 Manufacturers: TDK Corporation Description: BALUN 2.11-2.17GHZ 50/100 0603 In stock: Out stock RFQ	 HHM1776B3 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0603 In stock: Out stock RFQ
 HHM1763B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0603 In stock: Out stock RFQ	 HHM1902A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: Out stock RFQ
 HHM1776B2 Manufacturers: TDK Corporation Description: BALUN 824MHZ-894MHZ 50/50 0603 In stock: Out stock RFQ	 HHM1752A2 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 In stock: Out stock RFQ