



Maxim Integrated

MAX808LCSA+

Part Number: MAX808LCSA+
 Manufacturer/Brand: Maxim Integrated
 Product description: IC SUPERVISOR MPU 8-SOIC
 Datasheets: [1.MAX808LCSA+.pdf](#)
[2.MAX808LCSA+.pdf](#)
 RoHs Status: Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of MAX808LCSA+

| | |
|----------------------------------|--|
| PART NUMBER | MAX808LCSA+ |
| MANUFACTURER | Maxim Integrated |
| DESCRIPTION | IC SUPERVISOR MPU 8-SOIC |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| DATA SHEET | 1.MAX808LCSA+.pdf 2.MAX808LCSA+.pdf |
| VOLTAGE - THRESHOLD | 4.675V |
| TYPE | Battery Backup Circuit |
| SUPPLIER DEVICE PACKAGE | 8-SOIC |
| SERIES | - |
| RESET TIMEOUT | 140 ms Minimum |
| RESET | Active Low |
| PACKAGING | Tube |
| PACKAGE / CASE | 8-SOIC (0.154", 3.90mm Width) |
| OUTPUT | - |
| OPERATING TEMPERATURE | 0°C ~ 70°C (TA) |
| NUMBER OF VOLTAGES MONITORED | 1 |
| MOUNTING TYPE | Surface Mount |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited) |
| MANUFACTURER STANDARD LEAD TIME | 6 Weeks |
| LEAD FREE STATUS / ROHS STATUS | Lead free / RoHS Compliant |
| DETAILED DESCRIPTION | Supervisor 1 Channel 8-SOIC |
| BASE PART NUMBER | MAX808 |

Related Tags

| | | |
|------------------------------|--------------------------------|----------------------------------|
| Maxim Integrated MAX808LCSA+ | MAX808LCSA+ Distributor | MAX808LCSA+ Supplier |
| MAX808LCSA+ Price | MAX808LCSA+ Pictures | MAX808LCSA+ Image |
| MAX808LCSA+ PDF Datasheet | MAX808LCSA+ Download Datasheet | MAX808LCSA+ Datasheet |
| MAX808LCSA+ Stock | Buy MAX808LCSA+ | Buy Maxim Integrated MAX808LCSA+ |
| Maxim Integrated MAX808LCSA+ | Maxim Integrated Supplier | Maxim Integrated Distributor |
| Maxim Integrated MAX808LCSA+ | | |

Related Products

| | |
|---|---|
| <p>MAX807NEUE+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 16TSSOP In stock: 192 pcs RFQ</p> | <p>MAX807NEWE+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 16-SOIC In stock: 46 pcs RFQ</p> |
| <p>MAX808LESA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-SOIC In stock: 157 pcs RFQ</p> | <p>MAX808LCSA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-SOIC In stock: Out stock RFQ</p> |
| <p>MAX807NEPE+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 16-DIP In stock: Out stock RFQ</p> | <p>MAX807NEWE+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 16-SOIC In stock: Out stock RFQ</p> |
| <p>MAX808MCSA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-SOIC In stock: 58 pcs RFQ</p> | <p>MAX808LCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-DIP In stock: 593 pcs RFQ</p> |
| <p>MAX808LESA+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-SOIC In stock: Out stock RFQ</p> | <p>MAX808LEPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-DIP In stock: Out stock RFQ</p> |
| <p>MAX807NCWE+T Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 16-SOIC In stock: Out stock RFQ</p> | <p>MAX808MCPA+ Manufacturers: Maxim Integrated Description: IC SUPERVISOR MPU 8-DIP In stock: 100 pcs RFQ</p> |

